

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

*Not Authorized
 all
 1/17 #5364.50
 Take photo before parts
 3 days.
 11/9/22*

AIG ASIA PACIFIC INSURANCE PTE LTD
 AIG Building 78 Shenton Way #07-16
 079120

Attention : Motor Claim Department
 Contact : 6419 3000

Estimate : ES708469

Date : 07/09/2022
 Vehicle Num. : SMK 9995H
 Make/Model : MERCEDES E200
 Chassis/Eng# :
 Accident Date : 06/09/2022
 Claim No. :
 Reference : OD
 Policy No. :

S/N Quantity Particular Unit Price Amount S\$

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1 PC	BOOT LOGO <i>17</i>		105.00 <i>X</i>
2.	1 PC	BOOT EMBLEM E250 <i>17</i>		180.00 <i>X</i>
3.	1 PC	REAR BUMPER <i>20/22</i>		2,667.00 <i>X</i>
4.	2 PCS	REAR BUMPER SIDE RETAINER <i>17</i>	182.00	364.00 <i>X</i>
5.	1 PC	REAR BUMPER CENTER BRACKET <i>17</i>		256.00 <i>X</i>
6.	6 PCS	REVERSE SENSOR <i>305 x 2 = 610</i>	366.00	2,196.00 <i>2 pcs</i>
7.	6 PCS	REVERSE SENSOR ORING <i>17</i>	17.00	102.00 <i>X</i>
8.	6 PCS	REVERSE SENSOR BRACKET <i>28 x 6 = 168</i>	65.00	390.00 <i>X</i>
9.	1 PC	REAR BUMPER LOWER LIP <i>17</i>		680.00 <i>X</i>
10.	1 PC	REAR BUMPER LOWER LIP CHROME <i>466</i>		697.00 <i>X</i>
11.	1 PC	O/S REAR BUMPER REFLECTOR <i>17</i>		1,555.00 <i>X</i>
12.	1 PC	REAR BUMPER REINFORCEMENT <i>R</i>		375.00 <i>X</i>
13.	1 PC	O/S REAR EXHAUST CHROME <i>500</i>		375.00 <i>X</i>
List TotalS\$:				9,709.00
10.00% Discount S\$:				970.90
				8,738.10

S/N	Quantity	Particular	Unit Price	Amount S\$
SPECIAL NETT ITEMS :				
1.	1 PC	REAR BUMPER CLIP <i>17</i>		60.00 <i>50</i>
2.	1 PC	REAR BUMPER RIVET <i>17</i>		80.00 <i>50</i>

CONTINUE / ...

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

AIG ASIA PACIFIC INSURANCE PTE LTD
 AIG Building 78 Shenton Way #07-16
 079120

Attention : Motor Claim Department
 Contact : 6419 3000

Estimate : ES708469

Date : 07/09/2022
 Vehicle Num. : SMK 9995H
 Make/Model : MERCEDES E200
 Chassis/Eng# :
 Accident Date : 06/09/2022
 Claim No. :
 Reference : OD
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
3.	1 PC	REAR BUMPER LOWER LIP CLIP		60.00
4.	1 PC	REAR BUMPER LOWER RIVETS		80.00
Special Nett Total S\$:				280.00

LABOUR :

TO CHECK REAR PORTION WIRING
 TO FIT REVERSE SENSOR IN BUMPER
 TO RESET CLEARANCE SONAR USING DIAGNOSTIC SCANNER
 TO RUST PROOF PANELS
 TO REMOVE/REFIT GARNISH AND TRIMS TO FACILITATE REPAIRS
 TO REPAIR INNER PANEL, ACCIDENT DAMAGE AREA,
 REPLACEMENT OF PARTS AND ALIGN THE SAME
 TO PUTTY AND SPRAY PAINT ON ACCIDENT DAMAGE AREA
 TO REPAIR AND RE-ALIGN EXHAUST

20 50.00
 50 50.00
 80 400.00
 11 200.00 X
 60 280.00
 400 600.00
 600 900.00
 11 300.00 X

Labour Total S\$:

2,780.00

E. & O.E. Total S\$: 11,798.10
 =====

for FALCON AIR AUTO SERVICES PTE LTD

TAMPINES BRANCH

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

2-4505
 102
 4054.50
 100
 1210
 5364.50

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

AIG ASIA PACIFIC INSURANCE PTE LTD
 AIG Building 78 Shenton Way #07-16
 079120

Attention : Motor Claim Department
 Contact : 6419 3000

Supplementary Estimate : ES708504

Date : 26/09/2022
 Vehicle Num. : SMK 9995H
 Make/Model : MERCEDES E200
 Chassis/Eng# :
 Accident Date : 26/09/2022
 Claim No. :
 Reference : SUPPLY
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1 PC	LIST ITEMS : O/S REAR EXHAUST CHROME BRACKET		89.00 ✓
		List TotalS\$:		89.00
		10.00% Discount S\$:		8.90
				80.10
E. & O.E.			Total S\$:	80.10

for FALCON AIR AUTO SERVICES PTE LTD

TAMPINES BRANCH

PRECISE VULCANISE