LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.

79 Robinson Road #09-01 Singapore 068897 From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: JANICE KOH Date: 14 Sep 2022

Preliminary Advice

Vehicle No: SNA4452GAccident Date: 08/09/2022Make: HYUNDAI CN7 AVANTE 1.6Policy No.: SP2002032832

Assignment Date : 12/09/2022 Excess : \$\$0.00

Date of Inspection : 14/09/2022 Est. Duration of Repair : 12 days

Inspection At : KOMOCO MOTORS PTE LTD

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,805.76
Revised Amount	:S\$	11,509.65
Check Items (Estimated)	:S\$	889.20
Total	:S\$	12,398.85

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 110,000.00 COE / PARF Rebate :S\$ 46,317.00

Salvage Value :S\$

Margin for Repair :S\$ 63,683.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
	Kindly let us have your authorisation.

- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Part by Part repair.

Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.