

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 8922T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER (CONSISTENT)	DEFORMED	495.20	495.20
1	FRONT BUMPER SIDE HOLDER LH (CONSISTENT)	NOT NECESSARY	46.20	-
1	FRONT BUMPER FOG LAMP LH (CONSISTENT)	NOT NECESSARY	276.40	-
1	FRONT BUMPER FOG LAMP COVER LH (CONSISTENT)	CUT	128.50	128.50
1	HEADLAMP LH (CONSISTENT)	CRACKED	3,076.50	3,076.50
1	FRONT LH FENDER (CONSISTENT)	BUCKLED	713.20	713.20
1	FRONT LH FENDER INNER SHIELD (CONSISTENT)	DEFORMED	216.70	216.70
1	FRONT LH LOWER ARM (CONSISTENT)	BENT	486.30	486.30
1	FRONT LH SHOCK ABSORBER (CONSISTENT)	NOT NECESSARY	407.40	-
1	FRONT LH KNUCKLE ARM (CONSISTENT)	NOT NECESSARY	425.40	-
1	FRONT LH WHEEL HUB C/W BEARING (CONSISTENT)	DAMAGED	350.80	350.80
	LESS 25% DISCOUNT		-	-1,366.80
			6,622.60	4,100.40
	SPECIAL NETT ITEMS			
1	FRONT BUMPER CLIPS (CONSISTENT) (SN)	NECESSARY	30.00	30.00
1	FRONT LH FENDER INNER SHIELD CLIPS (CONSISTENT) (SN)	NECESSARY	30.00	30.00
1	FRONT LH WHEEL RIM (CONSISTENT) (SN)	NOT NECESSARY	300.00	-
1	FRONT LH WHEEL CAP (CONSISTENT) (SN)	CUT	200.00	120.00
1	FRONT LH TYRE (CONSISTENT) (SN)	NOT NECESSARY	300.00	-
			860.00	180.00
	LABOUR			
	PANEL BEATING.		800.00	400.00
	SPRAY PAINTING.		800.00	400.00
	WIRING.		50.00	30.00
	TO SPRAY TUFF COAT.		150.00	30.00
	TO REMOVE FRONT UNDERCARRIAGE.		350.00	120.00
	TO PERFORM WHEEL ALIGNMENT.		150.00	80.00
			2,300.00	1,060.00
	GRAND TOTAL		9,782.60	5,340.40

Report Ref No. CS/ASM22008925/Any3m4



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		4,200.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CS/ASM22008925/Any3m4



**ADRIAN LING WAI PING** 

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

**Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.