

**Main Office:**

 Mova Building  
 No. 22, Jalan Kilang,  
 Singapore 159419  
 Tel: (65) 6476 3333  
 Fax: (65) 6271 5891  
 www.mova.com.sg

**Workshop Dept:**

 Block 1008,  
 Bukit Merah Lane 3,  
 #01-04/06/08/94  
 Singapore 159722  
 Tel: (65) 6272 3892  
 Fax: (65) 6270 8314  
 Co. Reg. 198904033G  
 GST Reg. M2-0088864-2

**Estimate**
*Sten CLKK)*

31/08/2022

**CHINA TAIPING INSURANCE (S) PTE LTD**  
 3 Anson Road  
 #16-00 Springleaf Tower  
 Singapore 079909.

*S y  
 m R  
 PIP  
 by RL y*

 Page # :- 1  
 Veh # :- SLG6996H  
 Veh Model :- HYUNDAI AVANTE 1.6  
 Estimate# :- CK423902  
 Claim # :-  
 ACC. Date :- 07/09/22  
 Terms :- C.O.D Days  
 Remarks :-

Attention :- XA017

No.	Description	Qty	U.Price	Amounts S\$
<b>LIST ITEMS :</b>				
1.	FRONT FENDER LH / DD	1	1,227.00	1,227.00
2.	FRONT FENDER COWLING LH - CRV	1	185.00	185.00
3.	FRONT FENDER COWLING CLIPS - MK	10	3.90	39.00
4.	FRONT FENDER SIGNAL X	1	68.00	68.00
5.	FRONT WIPER GARNISH X	1	478.00	478.00
6.	FRONT SHOCK ABSORBER LH - BT	1	372.00	372.00
7.	FRONT SHOCK ABSORBER MOUNTING LH X	1	126.00	126.00
8.	FRONT KNUCKLE ARM LH X	1	412.00	412.00
9.	FRONT KNUCKLE BEARING LH X / JWD	1	396.00	396.00
10.	FRONT LOWER ARM X	1	298.00	298.00
11.	FRONT STG RACK END LH X	1	116.00	116.00
12.	FRONT STG TID ROD END LH X	1	104.00	104.00
13.	FRONT BUMPER RETAINER LH X	1	47.00	47.00
14.	FRONT BUMPER - TO REPAIR	1		
15.	FRONT BONNET - TO REPAIR	1		
16.	FRONT FENDER INNER PANEL LH - TO REPAIR	1		
17.	FRONT DOOR LH - TO REPAIR	1		
18.	HEADLAMP - TO CONFIRM	1		
	LIST TOTAL S\$			3,868.00
	20% DISCOUNT S\$			-773.60
				3,094.40
<b>SPECIAL NET ITEMS :</b>				
1.	FRONT ALLOY WHEEL LH X R	1	450.00	450.00
2.	FRONT TYRE LH X	1	250.00	250.00
	SPECIAL NET TOTAL S\$			700.00
<b>LABOUR :</b>				
	TO CUT & WELD, TO REPAIR FRONT DOOR LH, BONNET, INNER PANEL LH, FRONT BUMPER, TO REMOVE & REFIX DAMAGED PARTS, STRAIGHTEN & REALIGN AFFECTED AREAS		300	750.00
	TO SPRAY AFFECTED AREAS, BONNET, FRONT FENDER LH, FRONT DOOR LH, FRONT FENDER LH & AFFECTED AREAS		600	850.00
	TO REMOVE & REFIX FRONT UNDER CARRIAGE & FRONT SUSPENSION		170	180.00
	TO CHECK WHEEL ALIGNMENT		80	100.00
	TO DIAGNOSTIC WERE NECESSARY		30	100.00
	LABOUR TOTAL S\$			1,980.00

*biSAFE,*



Automotive Pte Ltd

# Estimate

31/08/2022

**CHINA TAIPING INSURANCE (S) PTE LTD**  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909.

Attention :- XA017

Page # :- 1 146635  
Veh # :- SLG6996H  
Veh Model :- HYUNDAI AVANTE 1.6  
Estimate# :- CK423902  
Claim # :-  
ACC. Date :- 07/09/22  
Terms :- C.O.D Days  
Remarks :-

**Main Office:**  
Mova Building  
No. 22, Jalan Kilang,  
Singapore 159419  
Tel: (65) 6476 3333  
Fax: (65) 6271 5891  
www.mova.com.sg

**Workshop Dept:**  
Block 1008,  
Bukit Merah Lane 3,  
#01-04/06/08/94  
Singapore 159722  
Tel: (65) 6272 3892  
Fax: (65) 6270 8314  
Co. Reg. 198904033G  
GST Reg. M2-0088664-2

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S	
AMOUNT S\$	5,774.40
GST @ 7 %	404.21
AMOUNT DUE S\$	6,178.61

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

bizSAFE<sub>3</sub>