

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

Sten CLKK

31/08/2022

CHINA TAIPING INSURANCE (S) PTE LTD

3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

*S y
m n
PIP
by RL y*

Page # :- 1

Veh # :- SLG6996H

Veh Model :- HYUNDAI AVANTE 1.6

Estimate# :- CK423902

Claim # :-

ACC. Date :- 07/09/22

Terms :- C.O.D Days

Remarks :-

Attention :- XA017

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

LIST ITEMS :				
1.	FRONT FENDER LH / <i>DD</i>	1	PC 1,227.00	1,227.00 ✓
2.	FRONT FENDER COWLING LH - <i>CR4</i>	1	PC 185.00	185.00 ✓
3.	FRONT FENDER COWLING CLIPS - <i>nk</i>	10	PC 3.90	39.00 ✓
4.	FRONT FENDER SIGNAL <i>x nn</i>	1	PC 68.00	68.00 ✓
5.	FRONT WIPER GARNISH <i>x nn</i>	1	PC 478.00	478.00 ✓
6.	FRONT SHOCK ABSORBER LH - <i>BT</i>	1	PC 372.00	372.00 ✓
7.	FRONT SHOCK ABSORBER MOUNTING LH <i>x nn</i>	1	PC 126.00	126.00 ✓
8.	FRONT KNUCKLE ARM LH <i>x nn</i>	1	PC 412.00	412.00 ✓
9.	FRONT KNUCKLE BEARING LH <i>x nn</i>	1	PC 396.00	396.00 ✓
10.	FRONT LOWER ARM <i>x nn</i>	1	PC 298.00	298.00 ✓
11.	FRONT STG RACK END LH <i>x nn</i>	1	PC 116.00	116.00 ✓
12.	FRONT STG TID ROD END LH <i>x nn</i>	1	PC 104.00	104.00 ✓
13.	FRONT BUMPER RETAINER LH <i>x nn</i>	1	PC 47.00	47.00 ✓
14.	FRONT BUMPER - TO REPAIR	1	PC	
15.	FRONT BONNET - TO REPAIR	1	PC	
16.	FRONT FENDER INNER PANEL LH - TO REPAIR	1	PC	
17.	FRONT DOOR LH - TO REPAIR	1	PC	
18.	HEADLAMP - TO CONFIRM	1	PC	

LIST TOTAL S\$ **2180** 3,868.00
20% DISCOUNT S\$ **-20%** -773.60

1744 + 20 nett

3,094.40

SPECIAL NET ITEMS :				
1.	FRONT ALLOY WHEEL LH <i>x R cut (local repair)</i>	1	PC 450.00 <i>109</i> ✓	450.00 ✓
2.	FRONT TYRE LH <i>x nn</i>	1	PC 250.00	250.00 ✓

SPECIAL NET TOTAL S\$

100

700.00

LABOUR :

TO CUT & WELD, TO REPAIR FRONT DOOR LH,
BONNET, INNER PANEL LH, FRONT BUMPER,
TO REMOVE & REFIX DAMAGED PARTS, STRAIGHTEN
& REALIGN AFFECTED AREAS

300 750.00

TO SPRAY AFFECTED AREAS, BONNET, FRONT
FENDER LH, FRONT DOOR LH, FRONT FENDER LH
& AFFECTED AREAS

600 850.00

TO REMOVE & REFIX FRONT UNDER CARRIAGE &
FRONT SUSPENSION

170 150 180.00

TO CHECK WHEEL ALIGNMENT

80 100.00

TO DIAGNOSTIC WERE NECESSARY

30 100.00

LABOUR TOTAL S\$

1130

1,980.00

biSAFE,



Automotive Pte Ltd

Estimate

31/08/2022

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- XA017

Page # :- 1 146635
Veh # :- SLG6996H
Veh Model :- HYUNDAI AVANTE 1.6
Estimate# :- CK423902
Claim # :-
ACC. Date :- 07/09/22
Terms :- C.O.D Days
Remarks :-

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088664-2

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S	
AMOUNT S\$	5,774.40
GST @ 7 %	404.21
AMOUNT DUE S\$	6,178.61

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

bizSAFE₃