

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: **SMW 2828R**
at Workshop m/s: **Specialists**
of _____
Insured: **SNA 5829Y**
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No: **SMW 2828R** Yr Regn: **22/03/19**
Type: **M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /**
Truck / Trailer or CAI
Make: **Land Rover Velar** c.c. **1997**
Colour: **Black** A/C: **Insured / Std / NI / NA**
Sp. Reading: **40821** T/Radio: **Insured / Std / NI / NA**
Eng/No: _____
C/No: _____
Gen. Cond: **Good / Fair / Poor / Burnt**
Steering: **Inorder / Jammed / Leaked / Burnt or**
Brake: **Inorder / Jammed / Leaked / Burnt or**
Modi: **Nil / S/Rim / STD A/Rim or**

(Policy Condition)
Remark: **The veh had commenced its repair at the time of inspection.**
Bal. or Market Value: **220k.**
IDAC Accident Rport: Consistent?: **Yes or No**
GIA / PR Seen: Consistent?: **Yes or No**
Est. Repairs: days Res.: **Yes or No**
Lum Sum: % 3 Val.: **Yes or No**

N/S	O/S

Tyre Size: F: **265/45R21** R: **PIR**
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Continental
Front Rear
R/Bal. **3** mm R/Bal. **3** mm
L/Bal. **3** mm L/Bal. **3** mm
D.O.A. **08/09/22** D.O.I. **14/09/22**
Survey held at _____

CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: **174 101998**
Vehicle: **IN / OUT**

Des. of Damages: **Frnt / Rear / O/S / N/S / U/C / Rooftop or**
Rec - N/S
The **U/C / Chassis frame / Body Structure** affected due to collision.

Date / Time Action / Instruction **Rp 20k.**
whole body have plastic sticker

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: _____

1) Date/Time, File Return to? _____

Resurvey No. of Trip: _____

2) _____

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$ _____)

Survey Fee: _____
Transportation: _____
) ___ S + RS ___ SI
) Photos
) Others

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	168I
Vehicle Details	
Vehicle No.:	SMW2828R
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Sep 2022
Vehicle Make:	LAND ROVER
Vehicle Model:	RANGE ROVER VELAR 2.0P 250PS R/D HSE S/R
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	181127Y0042PT204
Chassis No.:	SALYA2AXXKA207010
Maximum Power Output:	184.0 kW (246 bhp)
Open Market Value:	\$73,262.00
Original Registration Date:	22 Mar 2019
First Registration Date:	22 Mar 2019
Transfer Count:	1
Actual ARF Paid:	\$103,872.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Mar 2029
PARF Rebate Amount:	\$77,904.00
Intended COE Rebate Details	
COE Expiry Date:	21 Mar 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$36,961.00
COE Rebate Amount:	\$24,094.00
Total Rebate Amount:	\$101,998.00

51936

The information contained herein is correct as at 14 Sep 2022

OK

HOTTEST NEW CAR PROMOTIONS



Toyota Alphard
The ultimate family car! Supreme road presence with space for the whole family and much more.

DON'T MISS OUT!

Post an Advertisement
Sell it yourself! Advertise it at just **\$68 until it's SOLD!**

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

Toyota Dyna 150 3.0M



Low Mileage Unit, Only 1 Owner
Direct Owner StarAd

Republic Auto | **CERTIFIED PRE-OWNED MERCEDES BENZ**



[VIEW OUR CARS](#)

Sort by results/page

3 vehicles



land rover velar

Any Category

Advanced Search



Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	land rover velar		Any	Any	2019	Any	Any	Any	Available
	Land Rover Range Rover Velar 2.0A Si4 R-Dynamic		\$239,800	\$26,610 /yr	30-Dec-2019	1,997 cc	30,000 km	SUV	Available
1 owner. Full agent maintained. Low mileage. 5 years warranty and free servicing by agent. High loan available. Posted: 10-Sep-2022									
	Land Rover Range Rover Velar 2.0A Si4 R-Dynamic		\$249,000	\$27,660 /yr	31-Dec-2019	1,997 cc	39,000 km	SUV	Available
Like brand new, zero scratch. New Road Tax. Under Agent's warranty, fully serviced and maintained by Wearnes automotive, high ARF and low depre, generous cabin space and beautiful interior, full off-road capability, engaging yet comfortable driving. Trade in welcome. Flex... Posted: 09-Sep-2022									
	Land Rover Range Rover Velar 2.0A Si4 R-Dynamic HSE Sunroof		\$284,800	\$32,610 /yr	24-Oct-2019	1,997 cc	31,000 km	SUV	Available
Almost new unit available for immediate sale. Comprehensive warranty with attractive financing and insurance. The range rover velar takes glamour, modernity and elegance to an exceptional level with an emotionally charged DNA and unquestionable design pedigree. T... <input checked="" type="checkbox"/> This car comes with 6-mth Sgcar mart Warranty - the best protection for your car. Learn More Car House Pte Ltd Posted: 28-Jul-2022									

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view [Expired ads](#)

results/page

Buy / Rent Cars

[New Cars For Sale](#)

[Used Cars For Sale](#)

[Cars For Rent](#)

Sell Your Car

[Post an Ad](#)

[Sell by Bidding](#)

[Sell by Consignment](#)

Aftermarket

[Workshop Directory](#)

[Aftermarket Products](#)

[Bidded Carplates](#)

[Carpark Rates](#)

Articles

[Car Reviews](#)

[Car Advice](#)

[Car News](#)

[Car Features](#)

General

[About Us](#)

[Contact Us](#)

[Careers](#)

[Site Map](#)

Resources

[COE Prices](#)

[Car Loan Calculators](#)

[Car I Compare](#)

[Car Insurance](#)

[Car Valuation](#)

[COE Renewal](#)

[Used Car Warranty](#)

[Bidded Carplates](#)

[Carpark Rates](#)

Follow Sgcar mart.com



SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711
 Tel: 67472112 (5 lines) Fax: 67438032
 Email: cardoc@singnet.com.sg
 Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SMW2828R/2209118

12th September 2022

The Manager
 Motor Claim Department
 Auto & General Insurance (Singapore) Pte.Limited
 190 Clemenceau Avenue
 #03-01, Singapore Shopping Centre
 Singapore 239924

*not authorized
 her
 14/09/22
 L/S
 4 days.
 take photo after repair*

Date of Accident : 12th September 2022
 Location : Collyer Quay
 Third Party Claim Vehicle No : SNA 5829 Y
 Repair Cost For Vehicle No : SMW 2828 R Range Rover Velar

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts	
1	Rear bumper fascia upper <i>re/cut</i>	1	2,935.50	\$ 2,935.50	✓
2	Rear bumper fascia clip <i>re</i>	1set	67.50	\$ 67.50	✓
3	Rear bumper fascia side garnish LH <i>cut</i>	1	180.00	\$ 180.00	✓
4	Rear bumper fascia side garnish reflector LH <i>cut</i>	1	247.50	\$ 247.50	✓
5	Rear bumper fascia side retainer LH & RH <i>re</i>	2	142.50	\$ 285.00	X
6	Rear bumper fascia lower <i>cut</i>	1	435.00	\$ 435.00	✓
7	Rear bumper fascia lower reflector LH	1	112.50	\$ 112.50	?
8	Rear bumper parking sensor (centre LH) <i>re</i>	2	285.00	\$ 570.00	X
9	Rear bumper fascia diffuser upper <i>re</i>	1	825.00	\$ 825.00	✓
10	Rear boot cover emblem "velar P250 HSE" <i>re</i>	1	195.00	\$ 195.00	X
11	Rear boot cover emblem "Land Rover"	1	87.00	\$ 87.00	?
12	Rear bumper side bracket L&R <i>re</i>	2	105.00	\$ 210.00	X
13	Rear fender LH <i>re</i>	1	3,720.00	\$ 3,720.00	X
14	Rear boot cover <i>re</i>	1	3,825.00	\$ 3,825.00	X
15	Rear windscreen glass <i>re</i>	1	2,400.00	\$ 2,400.00	X
16	Rear windscreen sealant(s/nett) <i>re</i>	1	60.00	\$ 60.00	X
				<u>\$ 16,155.00</u>	

(102)

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SMW2828R/2209118

12th September 2022

Labour Charges :-

	<u>Amounts</u>
Balance b/f	\$ 16,155.00
Cut out, renew, knocking & welding Rear fender LH, rear end panel, remove & install all damage parts, straighten & re-align body	\$ 1,200.00
Tuff-kote on damage parts	11 \$ 40.00
Spray painting on damage parts	\$ 2,200.00
Remove & refix rear bumper sensor	\$ 100.00
Check all lighting after repairs	\$ 45.00
Remove & install rear windscreen glass	11 \$ 140.00
Labour Charge	<u>\$ 3,725.00</u>
Total Amount	<u>\$ 19,880.00</u>

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: