



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

-
SKF ENTERPRISE
27 MANDAI ESTATE #07-03
INNOVATION PLACE TOWER 2SINGAPORE
729931

Ref: CS/TP22008967/Rvy3

Date: 13/09/2022

Code: TP2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	GBB 4338R
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From FRANCIS WONG	Assign Date	09/09/2022

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date 03/06/2022	Inspection Date 09/09/2022
Survey held at SOON SENG HUAT 24 SUNGEI KADUT ST 4	
Repairer -	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.