(08/11/13) wef ASS. REC. BY: P grave	REF: CS	105 220	2003 n	Rvy3	*	4500	1	
		No. 1975	SIGNMEN'		SEP.			
From: D Estimated Cost: - OD / TP / WS / TP RES / OD RES / EV/	ate:		Veh No: Type: M.Car	SNG 410 / M.Cycle / Bus /	84 Van / Lorry	Yr Regn: 20	122 Ju Mover 1	my_
To Inspect Vehicle No: SNA 411 at Workshop m/s My Con C	JGN	1		TOYUTA LORO BLACK		S & H c.	c 79 § d/Std/N/	
of 60/31/11 Lyn Mark Insured: ECICS	₩05/7	ν ι	Sp.Reading Eng/No:	9176		T/Radio: Insure		/ NA
Policy No. Claims No.			C/No: Gen. Cond: 0	MAZBZ3		ov 9847		_
Sum Insured: E: (Client's Record)	xcess:		' \	rder / Jammed / L				
Make of Veh: (Policy Condition)	;	R	Modi : Nil Tyre Size:	F: STD A	Rim or 225/45	,R17		
Remark: The veh had commenced its repair at the time of inspection	on.	N/S O/S	TOYO / YO	XNOVA / GY / FS KO or	/ LIZA / MI	C / OHTSU / PI	R/SUMI/	
IDAC Accident Rport: Consis	Stent?: Yes or N		Front R/Bal.	C mm	•	R/Bal.)	mm
Est. Repairs: days	Res.: Yes or N Res.: Yes or N Val.: Yes or I	No	L/Bal. D.O.A. 03 Survey held a	6 mm 09 22 16 <u>M</u>		D.O.I. 13 U) 9/22 wt	_mm - -
CA / REV / REP. / 24 HRS Date: Person Contacted		icle: IN/OUT		ges: Frt / Rear				
Date / Time Action / Instruction REPAR LIMIT-	- 91K		The O/C	Chassis frame	r Body St	ructure affecte	d due to coll	lision.
		the second						
								* *** *** *** ***
	.75 1EN 36							
ate/Time, File Pass to? : Preli. R			Days Of Rep Resurvey No		Sec	Survey Fee:		
, and the control of		Add Fee				Transportation:		
Report Format : Lump Sum / I.B.I: (\$		##	: Tech.	ew (\$)	Photos Others		
-			vveek	end (\$)	TOTAL		

MY CAR CONSULTANT PTE LTD (Co Reg. No. 201605878Z) **60 JALAN LAM HUAT, CARROS CENTRE** #05-68 (S737869)

TO

: ECICS

:

DATE : 13-Sep-22

ATTENTION

: MOTOR CLAIMS DEPT

JOB TYPE : T/P CLAIM

VEHICLE DETAILS

VEHICLE NO : SNG4108U

MODEL

: TOYOTA ALTIS

THIRD PARTY REQUESTOR / CONTACT : DAUD/93911482

QUOTATION SUMMARY

CLAIM DETAIL: PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE		OTV		V		PRICE
1	FRONT BUMPER &/	1	\$	798.00	\$	798.00			
# 2	FRONT BUMPER LOWER GRILLE CM	1	\$	212.00	\$	212.00			
3	FRONT BUMPER SPONGE	1	\$	184.00	\$	184.00			
4	FRONT BUMPER UNDER COVER CM	1	\$	289.00	\$	289.00			
5	FRONT BUMPER REINFORCEMENT 1	1	\$	451.00	\$	451.00			
6	FRONT BUMPER SIDE RETAINER *	2	\$	98.00	\$	196.00			
7	FRONT GRILLE TOP RUBBER **/	1_	\$	75.00	\$	75.00			
8	FRONT GRILLE TOP GARNISH	1	\$	159.00	\$	159.00			
9	FRONT GRILLE	1	\$	590.00	\$	590.00			
10	FRONT GRILLE LOGO 🔼	1	\$	187.00	\$	187.00			
¥11	FRONT BUMPER LOWER GRILLE 🗡	1	\$	217.00	\$	217.00			
12	FRONT BUMPER LOWER COVER GARNISH RH 17.	1	\$	212.00	\$	212.00			
	FRONT BUMPER LOWER COVER GARNISH 4.7	1	\$	389.00	\$	389.00			
14	FRONT BUMPER FOG LAMP	2	\$	357.00	\$	714.00			
15	FRONT BUMPER FOG LAMP COVER 🗴	2	\$	130.00	\$	260.00			
16	FRONT WINDSCREEN GLASS CAL	1	\$	1,459.00	\$	1,459.00			
17	FRONT WINDSCREEN GLASS MOULDING /	1	\$	198.00	\$	198.00			
18	FRONT WIPER GARNISH X	1	\$	321.00	\$	321.00			
19	FRONT WIPER SIDE GARNISH RUBBER	1	\$	65.00	\$	65.00			
20	FRONT CHASSIS FRAME EXTENSION THEY	2	\$	785.90	\$	1,571.80			
21	FRONT SUPPORT PANEL 14/	1	\$	2,124.00	\$	2,124.00			
22	BONNET SW/	1	\$	1,354.00	\$	1,354.00			
23	BONNET LOWER LOCK SI/	1	\$	250.00	\$	250.00			

				_	
24	BONNET WEATHERSTRIP 🗡	1	\$ 68.00	\$	68.00
25	BONNET INSULATOR 6	1_	\$ 212.00	\$	212.00
26	BONNET HINGES 11/	1	\$ 62.00	\$	62.00
27	FRONT FENDER LY / raphy (LY / S)	2	\$ 658.00	\$	1,316.00
28	FRONT FENDER INNER PANEL X	2	\$ 588.80	\$	1,177.60
29	FRONT FENDER INNER SHIELD 🗡	2	\$ 198.00	\$	396.00
30	FRONT FENDER EMBLEM 'HYBRID' M	2	\$ 52.00	\$	104.00
31	FRONT WHEEL HOUSING 1	2	\$ 698.00	\$	1,396.00
32	FRONT FENDER GARNISH 🗡	2	\$ 55.00	\$	110.00
33	AIRCON CONDENSOR 6+/	1	\$ 1,568.00	\$	1,568.00
34	AIR CON SUCTION PIPE ?	1	\$ 580.00	\$	580.00
35	AIR CON PRESSURE PIPE ?	1	\$ 730.00	\$	730.00
36	AIR CON CONDENSOR LOWER RUBBER 7	2	\$ 32.50	\$	65.00
37	RADIATOR ?	1	\$ 1,780.00	\$	1,780.00
38	RADIATOR TOP GARNISH EM/	1	\$ 280.00	\$	280.00
39	RADIATOR TOP BRACKET ?	2	\$ 150.00	\$	300.00
40	RADIATOR MOUNTING ?	4	\$ 25.00	\$	100.00
41	RADIATOR FAN COWLING 7.	1	\$ 352.00	\$	352.00
42	RADIATOR FAN MOTOR 7.	1	\$ 364.00	\$	364.00
43	RADIATOR FAN BLADE	1	\$ 180.00	\$	180.00
44	RADIATOR HOSE TOTAL 7.	1	\$ 58.00	\$	58.00
45	RADIATOR TOP HOSE JOINT (T) TM -/	1	\$ 69.00	\$	69.00
46	RADIATOR LOWER HOSE ?	1	\$ 68.00	\$	68.00
47	BATTERY TOP BRACKET 🗡	1	\$ 68.00	\$	68.00
48	BRACE PANEL HT	1	\$ 195.00	\$	195.00
49	FRONT WIRE HARNESS 7.	1	\$ 1,458.50	\$	1,458.50
50	HEADLAMP CM/	2	\$ 2,985.00	\$	5,970.00
51 H	HEADLAMP CHROME MOULDING 💢	2	\$ 125.00	\$	250.00
52 H	HEADLAMP TOP PANEL 6+/	2	\$ 215.00	\$	430.00
53 H	HEAD LAMP LOWER BRACKET ?	4	\$ 58.00	\$	232.00
54 F	FRONT AIR DUCT (FLEXIBLE PIPE)	1	\$ 120.00	\$	120.00
	AIR CLEANER HOUSING CA	1	\$ 512.00	\$	512.00
	ENGINE TOP COVER 🗡	1	\$ 415.00	\$	415.00
57	ABS PUMP 🗡	1	\$ 2,170.00	\$	2,170.00
58	HYBRID INVERTOR 7 X	1	\$ 8,950.00	\$	8,950.00
59	HYBRID INVERTOR BRACKET X	1	\$ 159.00	\$	159.00
60	NTAKE MANIFOLD ?	1	\$ 1,280.00	\$	1,280.00
61	ALTERNATOR 4 X	1	\$ 1,129.00	\$	1,129.00

			- 1	- A	segmentes arrest
62	FUSE BOX 🗡	1	\$ 652.00	\$	652.00
63	AIRCON COMPRESSOR ×	1_	\$ 1,130.00	\$	1,130.00
64	ENGINE MOUNTING SET 7	1	\$ 851.00	\$	851.00
65	WIPER WASHER TANK	1	\$ 186.00	\$	186.00
66	WIPER WASHER TANK MOTOR 🗡	1	\$ 212.00	\$	212.00
67	COOLANT RESERVOIR	1	\$ 185.00	\$	185.00
68	RESONATOR BOX 7.	1	\$ 498.00	\$	498.00
69	FRONT DASHBOARD TIME	1	\$ 2,985.00	\$	2,985.00
70	FRONT DASHBOARD AIRBAG 447/	1	\$ 698.00	\$	698.00
71	STEERING AIRBAG 407/	1	\$ 698.00	\$	698.00
72	DRIVER FOOT AIRBAG	1	\$ 698.00	\$	698.00
73	FRONT SEAT BELT	2	\$ 840.00	\$	1,680.00
74	FRONT DOOR 61/ RH/LH-X	1/2	\$ 1,125.00	\$	2,250.00
75	REAR BUMPER de	1	\$ 698.00	\$	698.00
76	REAR BUMPER SENSOR MM	2	\$ 389.10	\$	778.20
77	REAR BUMPER REFLECTOR LH-X 14-7.	l 2	\$ 85.00	\$	170.00
	REAR BUMPER RETAINER /Lk-X NH-NH/	12	\$ 105.00	\$	210.00
	REAR BUMPER REINFORCEMENT	1	\$ 397.00	\$	397.00
80	REAR BUMPER REINFORCEMENT BRACKET	2	\$ 112.00	\$	224.00
81	AIR VENT X	1	\$ 65.80	\$	65.80
82	BOOTLID Y	1	\$ 989.00	\$	989.00
83	BOOTLID INNER TRIM de/	1	\$ 321.00	\$	321.00
84	BOOTLID REFLECTOR C/W CHROME	2	\$ 498.00	\$	996.00
	BOOTLID STOPPER N	4	\$ 75.00	\$	300.00
	BOOT LID HINGE X	2	\$ 212.00	\$	424.00
87	BOOTLID TOP LOCK 4/	1	\$ 398.00	\$	398.00
88	BOOTLID OUTER CHROME MOULDING 🗡	1	\$ 312.00	\$	312.00
89	BOOTLID LOWER LOCK 1	1	\$ 40.00	\$	40.00
90	BOOTLID WEATHERSTRIP W	1	\$ 220.00	\$	220.00
91	BOOTLID LOGO ~	1	\$ 75.00	\$	75.00
92	BOOTLID EMBLEM 'COROLLA'	1	\$ 65.00	\$	65.00
93	BOOTLID EMBLEM 'ALTIS"	1	\$ 75.00	\$	75.00
94	BOOTLID EMBLEM 'HYBRID"	1	\$ 68.00	\$	68.00
95	BOOTLID SENSOR ?	1	\$ 312.00	\$	312.00
96	BOOTLID NUMBER PLATE LAMP	2	\$ 62.00	\$	124.00
97	TAILLAMP C/W CHROME \$41	2	\$ 798.00	\$	1,596.00
	B TAILLAMP LOWER PANEL RHAP/LH-7.	2	\$ 320.00	\$	640.00
9	9 REAR WINDSCREEN GLASS MOULDING	1	\$ 112.00	\$	112.00

100	REAR FENDER LH-reput LH-IML/	12	\$ 1,024.00	\$ 2,048.00
737/99094	REAR FENDER INNER COWLING	2	\$ 358.00	\$ 716.00
102	REAR FENDER INNER TRIM 7,	2	\$ 770.00	\$ 1,540.00
103	REAR DOOR WEATHERSTRIP 🗡	2	\$ 198.00	\$ 396.00
	REAR DOOR INNER LOCK +	2	\$ 325.00	\$ 650.00
105	REAR END PANEL IM	1	\$ 695.00	\$ 695.00
106	REAR END PANEL TOP GARNISH &/	1	\$ 280.00	\$ 280.00
	REAR FLOOR PANEL 64/	1	\$ 1,025.00	\$ 1,025.00
108	REAR FLOOR PANEL TOP BOARD &	1	\$ 357.00	\$ 357.00
	REAR FLOOR PANEL TOP TOOLS SPONGE	1	\$ 398.00	\$ 398.00
	REAR FLOOR SIDE PANEL X	2	\$ 312.00	\$ 624.00
111	REAR EXHAUST HEAT SHIELD 🗡	1	\$ 251.00	\$ 251.00
112	REAR EXHAUST PIPE	1	\$ 956.00	\$ 956.00

TOTAL PRICE LESS 25% SUB TOTAL PRICE 79,218.90 19,804.73 5 59,414.18

S/N	DESCRIPTION	QTY	UN	UNIT S/NETT		AL S/NETT	
1	FRONT NUMBER PLATE	1	\$	50.00	\$	59.00	35
2	FRONT BUMPER CLIPS M	10	\$	6.50	\$	65.00	30
3	FRONT BUMPER LOWER GRILLE CLIP	8	\$	6.50	\$	52.00	30
4	FRONT BUMPER LOWER COVER GARNISH CLIP RH	/ 6	\$	6.50	\$	39.00	20
5	FRONT BUMPER LOWER COVER GARNISH CLIP LH	6	\$	6.50	\$	39:00	20
6	FRONT RADIATOR GRILLE CLIP	4	\$	6.50	\$	26.00	20
7	FRONT SUPPORT SEALANT	1	\$	80.00	\$	80.00	X
	FRONT WINDSCREEN GLASS SEALANT	1	\$	80.00	\$	80.00	40
	FRONT INDSCREEN GLASS INNER SEAL	1	\$	60.00	\$	60.00	40
8	REAR NUMBER PLATE	1	\$	50.00	\$	50.00	k
9	REAR BUMPER CLIPS	10	\$	6.50	\$	65.00	30
10	BATTERY & Cut	1	\$	300.00	\$	300.00	150
11	RADIATOR COOLANT M	1	\$	50.00	\$	50.00	30
12	BOOT LID INSULATOR CLIP ~/	10	\$	6.50	\$.	65.00	30
13	TAILLAMP CLIPS ~/	4	\$	8.00	\$	32.00	≈ 20
14	TAILLAMP PANEL SEALANT ~	12	\$	60.00	\$	120.00	30
15	REVERSE CAMERA 🗡	1	\$	450.00	\$	450.00	×
T 16	REAR FENDER SEALANT MAR / AH-RA/	12	\$	150.00	\$	300.00	60
17	REAR WINDSCREEN INNER SEAL	1	\$	50.00	\$	50:00	3
	REAR WINDSCREEN SEALANT	1	\$	60.00	\$	60.00	X/
} 19	REAR FENDER SEALANT	1	\$	80.00	\$	80.00	×

20	REAR FENDER COWLING CLIPS PH ~/	12	\$ 6.50	\$ 78:00 30
21	REAR FENDER INNER TRIMD CLIPS	12	\$ 6.50	\$ 78.00 🗶
22	REAR END PANEL TOP GARNISH CLIPS M	6	\$ 6.50	\$ 39.00
23	REAR END PANEL INSULATION SEAL ALL	1	\$ 150.00	\$ 150.00 40
24	REAR FLOOR PANEL SEALANT M/	1	\$ 120.00	\$ 120.00 40
25	REAR WHEEL HOUSING INSULATION SEAL	2	\$ 200.00	\$ 400.00

TOTAL \$ 2,978.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$1,800.00	1000	
2	SPRAY PAINTING TO AFFECTED AREA	\$1,600.00	1200	
3	WIRING CHECK	\$200.00	бо	
4	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$15ø.00	120	
5	REMOVE AND REFIX FRONT WINDSCREEN GLASS	\$150.00	120	
6	REMOVE AND REFIX FRONT DASHBOARD	\$400.00	180	
7	RADIATOR PRESSURE TEST	\$69.00	Yo	
8	RESET HYBRID TROUBLE CODE	\$600.00	×	
9	RE-ALIGN CHASSIS FRAME	\$250.00	80	
10	REFOCUS HEADLAMP BEAM	\$60.00	20	1,

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

PANEL BEATING, REMOVAL AND 1 REPLACING PARTS	\$2,600.00	1400	
2 TO SPRAY PAINT AFFECTED AREA	\$2,600.00	1200	
3 TUFF COAT	\$250.00	(W	

4	WIRING CHECK	\$80.00	60	
	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$300.00	80	
6	REMOVE AND REFIX REAR WINDSCREEN GLASS	\$120.00	120/	
	REMOVE AND REFIX REVERSE 7 SENSOR AND DISTANCE SETTING	\$80.00	ka Un	
	B REMOVE AND REFIX FUEL TANK	\$200.00	×	
	9 REAR CHASSIS ALIGNMENT	\$250.00	IOV	
1	TRANFER BOOTLID MECHANISM	\$60.00	· 40	
1	1 CONDUCT WATER LEAKAGE TEST	\$100.00	30	

TOTAL

\$12,110.00

TOTAL PARTS COST : \$ 62,392.18 : \$ 12,110.00 TOTAL LABOUR COST : \$ TOTAL REPAIR COST 74,502.18

LKK Auto Consultants hence notify the Repairer of the following:

· To resurvey before/after spray painting

- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Regater repr

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Actual Driver

- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by Interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 04/09/2022 17:46 (SGT)
Reported by Both
Date of Accident 03/09/2022 22:00 (SGT)
Exact Location of Accident Syed Alwi Rd, Singapore
Additional Location Information Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SNG4108U

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner FOCUS RENTALS PTE LTD
Company Reg No 2XXXXX450G
Email Address operations@focusrentals.sg
Mobile Phone No (Phone) +65-94516965
Alternative Phone No (Office) +65-98875600

VEHICLE PARTICULARS

Manufacturer Toyota

Model Corolla

Variant ALTIS

Exact purpose for which vehicle was being used at time of accident Private hire

Are you claiming under your own insurance policy for repair to your vehicle?

Vehicle Category

Transmission

CC

No - Claiming third party
Private hire
Auto
1798

INSURANCE COMPANY

Name of Insurance Company
Policy Number / Cover Note Number

India International Insurance Pte Ltd D20MFL0007747 01

DRIVER

Name of Driver NRIC No Date Of Birth Occupation

LIM HSEIN HON SXXXX005C 17/05/1980 Outdoor Date Of Driving Pass
Driving experience
Gender
Mobile Number
Alt. Phone Number
Email Address
Address
Address
Address complement
Postcode
Is the driver the policyholder?
If No, Relationship of the Driver with the Insured
Does Driver Own Other Vehicles?
Vehicle Registration Number of Other Vehicle Owned by Driver
Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
Weather Conditions
Road Surface

Chain Collision Clear Wet

22/01/2000

Male

461043

No

Hirer

22 YEARS AND 8 MONTHS

operations@focusrentals.sg

43 CHAI CHEE STREET #12-92

(Phone) +65-94516965

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 3 Was anybody injured in the Accident? Yes Was any injured conveyed to hospital by ambulance? Yes Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?
Translator's name No Translator's ID Translator's phone number Translator's email Original language used in the statement

DETAILS OF POLICE ACTION

Was the accident reported to the police?
Police Station Name
Police Station Phone No
Alt. Police Station Phone No
Police Station Address

Was notice of intended Prosecution given?
If yes, against whom?

Yes
Central Division Headquarters
(Phone) +65-18002240000
(Fax) +65-62200877
391 New Bridge Road #03-112 Police Cantonment Complex Block
A Singapore 088762

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO POLICE REPORT A/20220904/7020

ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera?

Yes No

No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number Vehicle Manufacturer Vehicle Model

SME1453P Toyota



Vehicle Variant	_
Vehicle Colour	_
Vehicle Category	Private car
Name of Driver	CHONG CHAN KWONG
Contact Number	(Phone) +65-98160973
Address	-
Address complement	
Postcode	
Insurance Company Name	•
Nature Of Damage	*
Nature Of Damage	1
Details of property damaged in accident	
No. Of Passenger (Including Driver)	<u> </u>

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKJ3954U
Vehicle Manufacturer	Audi
Vehicle Model	-
Vehicle Variant	_
Vehicle Colour	_
Vehicle Category	Private car
Name of Driver	LEE ZHI SHENG
NRIC No	SXXXX413D
Contact Number	(Phone) +65-98177436
Address	(Filone) +03-38177430
Address complement	
Postcode	450
Insurance Company Name	
Nature Of Damage	
Details of property damaged in accident	
No. Of December (Including Drive)	-:
No. Of Passenger (including Driver)	•

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	LIM HSEIN HON
Gender	-
Phone No	-
Address	1.
Address Complement	-
Post Code	3.
Approximate Age Years Old	\ -
Injuries Sustained	i.
Injured person in which vehicle?	CNC4400U
Were seat belts worn?	SNG4108U
West in in the second world	Yes
Was this injured conveyed to hospital by ambulance?	Yes

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- 5. Any false reporting may be referred to the Police for Investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurence Association
- of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act(PDPA)

l understand, acknowledge, agree and consent that :

- (a) My insurer . my w orkshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) w ho have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (i) Investigating the accident and/or my claims;
- (ii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (N) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

FLASH ACCIDENT REPORTING OFFICE FRO BALAJI

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

A.SNG4108U **B.SME1453P**

C.SKJ3954U

SYED ALWI ROAD



Describe Circumstances of the Accident REFER TO POLICE REPORT. Declaration FLASH ACCIDENT FRO BALAJI Policyholder's Signature / Date & Driver's Signature (If driver is not the policynoider) / Date Witnessed by Reporting Centre

04/09/22 1500HRS

> Back to One Motoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company	
Owner ID:	450G	
Vehicle No.:	SNG4106U	
Vehicle to be Exported:	PERSONAL NO. OF THE PROPERTY O	
ntended Deregistration Date:	14 Sep 2022	
Vehicle Make:	TOYOTA	
Vehicle Madel:	COROLLA ALTIS 4DR SEDAN (AT)(2WD) HYBRID	
Primary Colour:	ATTENDED TO A LONG TO LONG TO A LONG	
Manufacturing Year:	2022	
Engine Na:	2ZRY856279	
Chassis No.:	MR28Z3BE000009847	
Maximum Power Output:	90.0 kW (120 bhp)	
Open Market Value:	\$24,985.00	
Original Registration Date:	29 Jul 2022	
First Registration Date:	29 Jul 2022	
Transfer Count: -		
Actual ARF Paid:	\$11,979.00	
PARF Eligibility:	TO THE YES ALL PROPERTIES OF THE COMPANY OF THE CAME O	
PARF Eligibility Expiry Date:	28 Jul 2032	
PARF Rebate Amount:	\$8,984.00	
COE Expiry Date:	28 Jul 2032	
COE Category:	B- Car-Details at OneMotoring	
COE Period(Years):		
QP Paid:	\$95,889.00	
COE Rebate Amount:	\$94,651.00	
Total Rebate Amount:	\$103,635.00	

The information contained herein is correct as at 14 Sep 2022

Toyota Corolla Altis Hybrid

Overview

Pricing

Photos

Research


Reviews

Specs

Feature

Borne

Shortlist | Submit a Review | Propert Error | Share



Hotline 66311 09-9 **Pricelist** » View all Toyota cars

Distributor

New Car Dealer I

Toyota Corolla Altis Hybrid Price History

Date Updated 09-Sep-2022

Submodel Pricing Information

1.8 (A)

Current price

- Depreciation
- Down Payment
- Installment COE quota premium
- Road tax
- OMV 🔞
- ARF
- VES
- Total basic cost

Dramium

View Loan Breakdown

\$199,888

\$19,400 /yr

\$79,955 (Maximum 60% loan)

\$1,706 /mth

\$113,000 (Category B COE)

\$976 /yr

\$24,999

\$11,999 (After VES rebates)

\$15,000 (Rebate)

\$157,320

770/