



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: TEO KITTY			Ref: CS/ASM22009004/Uvy3e2 Date: 13/10/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLJ 4861K	Veh. Inspected	SLW 8200Z	
Policy No.	GA156839	Coverage (\$)	0.00	
Claim No.	S2M04A11	Excess (\$)	0.00	
Assign From	TEO KITTY	Assign Date	13/09/2022	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. 523i (A)	c.c	2497	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	WBAFP32070C867816	Colour	GREY	
Odometer	177318 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	255/35Z R20	CONTINENTAL	6 mm	
L/H Front Tyre	255/35Z R20	CONTINENTAL	6 mm	
R/H Rear Tyre	265/35Z R20	CONTINENTAL	6 mm	
L/H Rear Tyre	265/35Z R20	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/08/2022	Inspection Date	14/09/2022	
Survey held at	MAH LIAN MOTOR VEHICLE REPAIRER 38 DEFU LANE 9 SINGAPORE 539278			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	