

## Veron Chen (LKKAUTO)

---

**From:** Rasul (LKKAUTO)  
**Sent:** Tuesday, 7 March 2023 12:08 PM  
**To:** SUR; CS A Team  
**Subject:** FW: OD Ergo Insurance GBK9340C RE: item 35 missing on my estimate marked GBK9340C RE: GBK9340C-OD-ERGO  
**Attachments:** SKM\_C250i23030711530.pdf

---

**From:** William Auto <waplsp21@singnet.com.sg>  
**Sent:** Tuesday, 7 March 2023 12:07:28 pm (UTC+08:00) Kuala Lumpur, Singapore  
**To:** Rasul (LKKAUTO) <Rasul@lkkauto.com>  
**Subject:** OD Ergo Insurance GBK9340C RE: item 35 missing on my estimate marked GBK9340C RE: GBK9340C-OD-ERGO

Dear Mr Rasul  
Enclosed Final Bill ( Ergo Insurance O/D ) of GBK9340C for your kind perusal  
Thank you  
William Ang

---

**From:** Rasul (LKKAUTO) [mailto:Rasul@lkkauto.com]  
**Sent:** Wednesday, 22 February 2023 9:01 am  
**To:** William Auto <waplsp21@singnet.com.sg>  
**Subject:** Re: item 35 missing on my estimate marked GBK9340C RE: GBK9340C-OD-ERGO

Hi William,

Kindly acknowledge

Best Regards,

**Rasul** | Assessor

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Rasul@lkkauto.com](mailto:Rasul@lkkauto.com) | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



*Save the Earth. Print only when necessary.*

---

**From:** Rasul (LKKAUTO) <[Rasul@lkkauto.com](mailto:Rasul@lkkauto.com)>  
**Sent:** Monday, 13 February 2023 10:26 am  
**To:** William Auto <[waplsp21@singnet.com.sg](mailto:waplsp21@singnet.com.sg)>  
**Subject:** Re: item 35 missing on my estimate marked GBK9340C RE: GBK9340C-OD-ERGO

Hi Mr William,

As spoken, the finalised amount is P/P \$ 6,287.81/ 5 days of repair

Kindly acknowledge

Best Regards,

Rasul | Assessor

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Rasul@lkkauto.com](mailto:Rasul@lkkauto.com) | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



*Save the Earth. Print only when necessary.*

---

**From:** William Auto <[waplsp21@singnet.com.sg](mailto:waplsp21@singnet.com.sg)>

**Sent:** Friday, 10 February 2023 11:00 am

**To:** Rasul (LKKAuto) <[Rasul@lkkauto.com](mailto:Rasul@lkkauto.com)>

**Subject:** item 35 missing on my estimate marked GBK9340C RE: GBK9340C-OD-ERGO

Dear Rasul

Please check the missing Item 35 on estimate marked S. Nett \$20.00,

The correct amounts should be \$6,287.81.

Please revert to me ASAP

Thank you

William Ang

---

**From:** Rasul (LKKAuto) [<mailto:Rasul@lkkauto.com>]

**Sent:** Friday, 10 February, 2023 8:35 AM

**To:** William Auto <[waplsp21@singnet.com.sg](mailto:waplsp21@singnet.com.sg)>

**Subject:** Re: GBK9340C-OD-ERGO

Hi Mr William,

refer to attachment

Audit checked some parts prices required verification. We will be advising our principal a cost of repair P/P \$6,267.81/- with 05 days of repair subject to their approval.

Kindly acknowledge

Best Regards,

Rasul | Assessor

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Rasul@lkkauto.com](mailto:Rasul@lkkauto.com) | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



*Save the Earth. Print only when necessary.*

---

**From:** William Auto <[waplsp21@singnet.com.sg](mailto:waplsp21@singnet.com.sg)>

**Sent:** Wednesday, 14 September 2022 5:07 pm

**To:** Rasul (LKKAuto) <[Rasul@lkkauto.com](mailto:Rasul@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Subject:** GBK9340C-OD-ERGO

**From:** [wapls21@singnet.com.sg](mailto:wapls21@singnet.com.sg) [<mailto:wapls21@singnet.com.sg>]

**Sent:** Wednesday, 14 September, 2022 3:34 PM

**To:** [wapls21@singnet.com.sg](mailto:wapls21@singnet.com.sg)

**Subject:** Message from KM\_C250i