

WILLIAM'S AUTO PTE LTD

BLK c3 WOODLANDS ROAD 391-B YEW TEE INDUSTRIAL ESTATE SINGAPORE 677965
TEL: 67636811 FAX: 67632166 Email: waplsp21@singnet.com.sg
GST:M2-0032987-2 RCB NO:A03151/1978Z

M/S : ERGO INSURANCE PTE LTD
8 TEMASEK BOULEVARD #04-01
SUNTEC TOWER THREE
SINGAPORE 038988

TEL: 68299199 - FAX: 68299247,68299248
claims@ergo.com.sg

ATTN: Motor Claim Department

Your Ref No: GBK9340C
Claim Type: Own Damage
Accident Date: 12/09/2022

Final No: CL2301073
Claim No: EST2201077
Date: 02 Mar 2023
Policy No: DMCG22000704
Veh Reg No: GBK9340C
Make/Model: TOYOTA DYNA 150
5MT
Chassis No: JTFAT35YX0K216252
Engine No: 1KDB068625
Reg. Date: 25/01/2021

Tax Invoice to Vehicle No :GBK9340C

PAGE:1

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
AS LUMP SUM REPAIRS (INCL. PARTS & LABOURS)	1 PC	S\$ 6,287.81	S\$ 6,287.81
Total			S\$ 6,287.81
Less Excess			S\$ 1,300.00
Amount Before GST			S\$ 4,987.81
Add GST @ 7%			349.15
Total Amount payable			<u>S\$ 5,336.96</u>

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND THREE HUNDRED THIRTY SIX AND CENTS
NINETY SIX ONLY

The above vehicle was surveyed by LKK AUTO CONSULTANTS PTE LTD on 15/09/2022

For WILLIAM'S AUTO PTE LTD

AUTHORISED SIGNATURE

E. & O. E.

WILLIAM'S AUTO PTE LTD

BLK c3 WOODLANDS ROAD 391-B YEW TEE INDUSTRIAL ESTATE SINGAPORE 677965

TEL: 67636811 FAX: 67632166 Email: waplsp21@singnet.com.sg

GST:M2-0032987-2 RCB NO:A03151/1978Z

M/S : ERGO INSURANCE PTE LTD
8 TEMASEK BOULEVARD #04-01
SUNTEC TOWER THREE
SINGAPORE 038988

TEL: 68299199 - FAX: 68299247,68299248

ATTN: Motor Claim Department

Your Ref No: GBK9340C
Claim Type: Own Damage
Accident Date: 12/09/2022

Claim No: EST2201077

Final No: CL2301073

Date: 02 Mar 2023

Policy No: DMCG22000704

Veh Reg No: GBK9340C

Make/Model: TOYOTA DYNA 150
5MT

Chassis No: JTFAT35YX0K216252

Engine No: 1KDB068625

Reg. Date: 25/01/2021

Tax Invoice to Vehicle No : GBK9340C

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 FRONT CORNER PANEL - LH		1 PC	296.45	296.45
2 FRONT CORNER PANEL INNER BRACKET - LH		1 PC	49.20	49.20
3 FRONT GRILLE		1 PC	393.20	393.20
4 FRONT GRILLE SEAL		1 PC	69.70	69.70
5 HEAD LAMPS LH		1 PC	1,589.40	1,589.40
6 HEAD LAMP LOWER SEAL - LH		1 PC	78.50	78.50
7 FRONT DOOR V - LH		1 PC	985.20	985.20
8 FRONT DOOR FRONT COVER GARNISH - LH		1 PC	96.80	96.80
9 FRONT DOOR RUBBER - LH		1 PC	245.70	245.70
10 FRONT DOOR LOWER SEAL - LH		1 PC	96.90	96.90
11 FRONT DOOR HINGE - RH - LH		1 PC	78.10	78.10
12 FRONT DOOR LOCK - RH - LH		1 PC	257.30	257.30
13 FRONT DOOR CATCH - RH - LH		1 PC	96.50	96.50
14 FRONT DOOR CHECKER - LH		1 PC	98.70	98.70
15 FRONT DOOR INNER TRIMBOARD LH		1 PC	698.60	698.60
16 FRONT DOOR PILLAR OUTER - LH		1 PC	497.80	497.80
17 FRONT DOOR PILLAR RUBBER LH		1 PC	239.20	239.20
18 FRONT SIDE MIRROR STAY - LH		1 PC	479.20	479.20
19 FRONT SIDE MIRROR (BIG) - LH		1 PC	267.30	267.30
20 FRONT DOOR PILLAR COVER GARNISH - LH		1 PC	138.70	138.70
21 FRONT WHEEL ARCH PANEL SIDE SEAL - LH		1 PC	119.70	119.70
22 FRONT FLOOR PANEL		1 PC	1,557.50	1,557.50
23 FRONT CABIN LOWER STEP GARNISH - LH		1 PC	214.90	161.18
24 FRONT CABIN LOWER STEP OUTER PANEL - LH		1 PC	247.40	185.55
25 FRONT BUMPER		1 PC	423.90	423.90
26 FRONT BUMPER BRACKET		1 PC	267.10	267.10
27 FRONT BUMPER FOG LAMP COVER LH		1 PC	98.50	98.50
28 AIR-CON LIQUID PIPE		1 PC	297.20	297.20
29 AIRCON DISCHARGE PIPE		1 PC	379.20	379.20
30 AIR CON CONDENSER FAN ASSY		1 PC	695.70	695.70
31 AIRCON CONDENSER		1 PC	1,078.60	1,078.60
32 AIRCON CONDENSER BRACKET		1 PC	289.10	289.10
33 AIRCON RECEIVER DRIER		1 PC	197.40	197.40
34 FRONT WHEEL RIM - LH		1 PC	398.10	398.10
				12,901.18
Special Net				
35 FRONT DOOR SIDE LETTERING/PANEL MARKER LH		1 PC	20.00	20.00

WILLIAM'S AUTO PTE LTD

BLK c3 WOODLANDS ROAD 391-B YEW TEE INDUSTRIAL ESTATE SINGAPORE 677965

TEL: 67636811 FAX: 67632166 Email: waplsp21@singnet.com.sg

GST:M2-0032987-2 RCB NO:A03151/1978Z

M/S : ERGO INSURANCE PTE LTD
8 TEMASEK BOULEVARD #04-01
SUNTEC TOWER THREE
SINGAPORE 038988

TEL: 68299199 - FAX: 68299247,68299248
ATTN: Motor Claim Department

Your Ref No: GBK9340C
Claim Type: Own Damage
Accident Date: 12/09/2022

Claim No: EST2201077
Final No: CL2301073
Date: 02 Mar 2023
Policy No: DMCG22000704
Veh Reg No: GBK9340C
Make/Model: TOYOTA DYNA 150
5MT
Chassis No: JTFAT35YX0K216252
Engine No: 1KDB068625
Reg. Date: 25/01/2021

Tax Invoice to Vehicle No : GBK9340C

Description	U/Price	Quantity	Cost	Amount
			S\$	S\$
36 FRONT DOOR INNER TRIMBOARD CLIPS - LH		1 SET	65.00	65.00
37 FRONT CABIN LOWER STEP GARNISH CLIPS - LH		1 PC	20.00	20.00
				105.00
To Repair				
38 FRONT CABIN LOWER STEP INNER PANEL - LH		1 PC	471.40	0.00
				0.00
Labour				
39 LABOUR TO REMOVE DAMAGED PARTS & ATTACHMENTS,JACK,STRAIGHTEN,CUT,WELD,REPAIR AND RESHAPE DENTED PANELS RENEW DAMAGED PANELS AND PARTS ALIGN AND REFIT ATTACHMENTS THE SAME.		1 JOB	1,200.00	1,200.00
40 LABOUR TO TRANSFER DAMAGED FRONT DOOR-LH ATTACHMENTS TO NEW DOOR.		1 JOB	80.00	80.00
41 LABOUR TO AIRCON JOB,CHECK,CHANGE PARTS AND REFILL GAS.		1 JOB	180.00	180.00
42 TO RESPRAY PAINTING ON REPLACEMENT PARTS AND OTHER AFFECTED AREAS		1 JOB	1,200.00	1,200.00
43 LABOUR TO REMOVE UPHOLSTERY SEATS,TRIM BOARD,INNER COVER GARNISH ENABLE NECESSARY REPAIR WORKS.		1 JOB	150.00	150.00
44 LABOUR TO REMOVE,CHECKUNDER CARRIAGE AND REPALCE NEW RIM.		1 JOB	120.00	120.00
45 LABOUR TO CONDUCT 4XWHEEL ALIGNMENT		1 JOB	90.00	90.00
				3,020.00

WILLIAM'S AUTO PTE LTD

BLK c3 WOODLANDS ROAD 391-B YEW TEE INDUSTRIAL ESTATE SINGAPORE 677965
TEL: 67636811 FAX: 67632166 Email: waplsp21@singnet.com.sg
GST:M2-0032987-2 RCB NO:A03151/1978Z

M/S : ERGO INSURANCE PTE LTD
8 TEMASEK BOULEVARD #04-01
SUNTEC TOWER THREE
SINGAPORE 038988

TEL: 68299199 - FAX: 68299247,68299248
ATTN: Motor Claim Department

Your Ref No: GBK9340C
Claim Type: Own Damage
Accident Date: 12/09/2022

Claim No: EST2201077
Final No: CL2301073
Date: 02 Mar 2023
Policy No: DMCG22000704
Veh Reg No: GBK9340C
Make/Model: TOYOTA DYNA 150
5MT
Chassis No: JTFAT35YX0K216252
Engine No: 1KDB068625
Reg. Date: 25/01/2021

Tax Invoice to Vehicle No : GBK9340C

Total	S\$ 16,026.18
Lump Sum Less 60.7654%	-9,738.37
Amount Before Excess	S\$ 6,287.81
Less Excess	S\$ 1,300.00
Amount Before GST	S\$ 4,987.81
Add GST @ 7%	349.15
Total Amount payable	S\$ 5,336.96

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND THREE HUNDRED THIRTY SIX AND CENTS NINETY SIX ONLY

The above vehicle was surveyed by LKK AUTO CONSULTANTS PTE LTD on 15/09/2022

For WILLIAM'S AUTO PTE LTD

AUTHORISED SIGNATURE

E. & O. E.