

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

	INCOME INSURAN	ICE LTD	-	Ref:	CS3/INC22009014/Gny3	
	73 BRAS BASAH R #05-01 NTUC TRA 189556	ROAD DE UNION HOUSESINGAPORE		Date:	13/09/2022	
				Code:	INC	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SNE 8818M	Veh. Inspected	i	SKX 171H	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1188371-001	Excess (\$)		0.00	
	Assign From	HAZALYSA BINTE IBRAHIM	Assign Date		13/09/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5.	General Information					
	Accident Date	11/09/2022	Inspection Dat	e	13/09/2022	
	Survey held at	D'S GRAFFITI CONCEPTS PTE	LTD			
		8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					