




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: TEO KITTY			Ref: CS3/ASM22009030/Rvy3m4 Date: 19/09/2022 Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SLX 1437Z	Veh. Inspected	SNA 2888X
	Policy No.		Coverage (\$)	0.00
	Claim No.	S2M04AY3	Excess (\$)	0.00
	Assign From	TEO KITTY	Assign Date	14/09/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HARRIER ELEGANCE 2.0 A	c.c	1986
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	ZSU600028158	Colour	WHITE
	Odometer	89538 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/60 R18	PIRELLI	6 mm
	L/H Front Tyre	235/60 R18	PIRELLI	6 mm
	R/H Rear Tyre	235/60 R18	PIRELLI	6 mm
	L/H Rear Tyre	235/60 R18	PIRELLI	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S & REAR PORTION.			
5. General Information				
	Accident Date	12/09/2022	Inspect Date / Time	14/09/2022 (01:58 PM)
	Survey held at	KUM CHEW MOTOR WORKSHOP 160 SIN MING DRIVE #05-08 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$9,000-\$10,000			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	

Report Ref No. CS3/ASM22009030/Rvy3m4

Inspected By

MRB

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.