

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/GRB22009042/KCY3M4**Date:** 30/09/2022REFERENCE

Insured/Claimant: GRAB RENTALS PTE LTD Policy No: D21MFL0000447_01
Date of Loss: 12/09/2022 Nature of Claim: OD Claim No: MFL2022D0005201

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLR7284P**
Make & Model: HONDA VEZEL HYBRID, 1.5 x (A) Engine No: LEB5922495
Reg. Date: 25/08/2017 (Man. Year: 2016) Chassis No: RU31222484
Colour: Metallic Green Odometer: 0 km
Engine Capacity: 1496 cc
Market Value/New Car Price: S\$66,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: TRISTAR 8 mm Rear Left Side: TRISTAR 7 mm
Front Right Side: TRISTAR 8 mm Rear Right Side: TRISTAR 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 14/09/2022
Date Inspected: 14/09/2022 Inspected At: Esteem Performance Pte Ltd (HQ)
176 Sin Ming Autocare Sin Ming Drive, #01-14 & #01-15 & #01-16
Singapore 575721
Estimated Period of Repair: 0.0 days

Adjuster: KENNETH KONG**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$66,000.00
OMV :	\$27,443.00
PARF Rebate (1) :	\$3,500.00
Quota Premium Paid :	\$50,110.00
COE Rebate (2) :	\$23,290.00
Total Rebate (1) + (2) = :	\$26,790.00

The total amount incurred will be Market Value \$66,000.00 minus Total Rebate \$26,790.00 = \$39,210.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Sep 2022)

Parts: M1-SUV HONDA VEZEL HYBRID 1.5 x (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLR7284P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >