

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Sharon Lim

Date: 16 Sep 2022

**Preliminary Advice**

Vehicle No	: SJN3879U	Accident Date	: 10/09/2022
Make	: HYUNDAI AVANTE	Policy No.	: SP2001439724
Assignment Date	: 15/09/2022	Excess	: S\$600.00
Date of Inspection	: 16/9/2022	Est. Duration of Repair	: 7
Inspection At	: MOVA AUTOMOTIVE PTE LTD		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,375.50
Revised Amount	:S\$	9,472.20
Check Items (Estimated)	:S\$	1,713.30
Total	:S\$	11,185.50

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	13,000.00
COE / PARF Rebate	:S\$	3,622.00
Salvage Value	:S\$	
Margin for Repair	:S\$	9,378.00

**Remarks**

( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( X ) Other comments : Lump Sum Repair

Repairer able to undertake the repair Not Exceeding the Nett Value \$9,378.00

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .