

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 436180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

13/9/22

Estimate No. : b1 63225
Date Estimated : 06/09/2022
Prepared By : Yap Mee Key

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

WORLD F PTE LTD
47 TOH TUCK PLACE
TOH TUCK GARDEN

SINGAPORE 596822

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMX6055Y	WBA32AA0605S53433	21/01/2021	X1 sDrive18i	20192

DESCRIPTION**VALUE**

To replace taigate, rear bumper carrier and rear bumper. 1/2 mil

2125 ✓ 3,400.00

To respray taigate and rear bumper.

1972 ✓ 2,076.00

To replace rear exhaust silencer including alignment system and conduct check for leak.

X 531.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

168 ✓ 177.00

To check electrical.

168 ✓ 177.00

To replace rear windscreen glass.

545 ✓ 574.00

To supply and install rear windscreen solar film.

544 X 531.00

To conduct water leak tests.

71 ✓ 75.00

To carry out body cavity preservation.
(Per panel).

112 ✓ 118.00

To transfer lock mechanism from old to new bootlid including conduct check on new bootlid central locking system for proper function.

594 ✓ 531.00

Sundries.

150.00 ✓

Total Labour 1: **8,340.00****DESCRIPTION****QTY****PRIC****VALUE**

RUBBER MOUNTING

3

18.15

54.45

TAILPIPE TRIM BRIGHT CHROME

1

125.55

125.55

REAR SILENCER

1

1,108.15

1,108.15

BOOTLID

1

1,298.95

1,298.95 ✓

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 63225
Date Estimated : 06/09/2022
Prepared By : Yap Mee Key

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMX6055Y	WBA32AA0605S53433	21/01/2021	X1 sDrive18i	20192

DESCRIPTION	QTY	PRIC	VALUE
REAR BUMPER TRIM PANEL (X LINE) / CUT	1	226.95	226.95 ✓
RR BUMPER CARRIER X NN	1	523.75	523.75
REAR BUMPER PANEL PRIMED X NN	1	907.80	907.80
REAR BUMPER MIDDLE TRIM PANEL (PDC) / CUT	1	266.90	266.90 ✓
PLUG IN NUT X NN	10	3.10	31.00
REAR BUMPER TOWING EYE COVER X NN	1	37.70	37.70
REAR WINDOW (ESG) / APC	1	815.55	815.55 ✓
BOOTLID SEALING X NN	1	169.85	169.85
(DG) CLEANER R1 (100ML) / APC	1	26.15	26.15 ✓
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) / APC	2	131.55	263.10 ✓

Total Parts : 5,855.85

Steve (LKK)
21/9/22, 10.30am

W/L PL
P/P
by BEL by
5 dys

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	8,340.00
Parts	:	5,855.85
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	993.71
Grand Total	:	15,189.56

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **