



SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road, Singapore 758133
T 65 6758 2222 F 65 6257 6931
E sales@scauto.com.sg
scauto.com.sg

Co. Reg. No. 199800107D

ESTIMATE BILL

GST Reg. No: 199800107D
Date: 16/9/2022
Our Case Ref: SC22/09/122/4TT-TP
Accident Date: 12/9/2022

M/S CHINA TAIPING INSURANCE (S)
PTE LTD
3 ANSON RD, #16-00 SPRINGLEAF
TOWER, SINGAPORE 079909
Insured TONG TAR TRANSPORT SVC PTE LTD
Policy 5128761629

Damaged Vehicle No: PC4513E

S/no	Description	QTY	Price	Amount	Remark
Replaced Parts					
1	REAR BUMPER <i>Re</i>	1 PC	\$1,980.50	\$ 1,980.50	✓ NETT
2	REAR NUMBER PLATE <i>BT</i>	1 PC	\$ 80.00	\$ 80.00	50 ✓ NETT
3	TAILGATE <i>X Repair</i>	1 PC	\$2,660.50	\$ 2,660.50	X
4	REAR NUMBER PLATE LIGHT <i>Q/S</i>	2 PC	\$ 855.00	\$ 855.00	✓ NETT
5	BODY STICKER <i>L-SET</i>	1 SET	\$1,700.00	\$ 1,700.00	800 ✓ NETT
6	SUNDRIES <i>Y.M.C.</i>		\$ 200.00	\$ 200.00	50 ✓ NETT
				3735.50	
LABOUR CHARGES					
1	LABOUR TO REMOVE AND REINSTALL REAR WIRE HARNESS AND CHECK INTERIOR WIRING ACCORDING TO DAMAGE		\$ 500.00	\$ 500.00	X <i>an</i>
2	LABOUR TO REMOVE AND REINSTALL BODY STICKER		\$ 800.00	\$ 800.00	<i>640</i> X <i>NN</i>
3	LABOUR TO REMOVE, REINSTALL AND REPAIR REAR BUMPER AND REAR PANEL INNER, REAR LID		\$ 3,200.00	\$ 3,200.00	<i>640</i> ✓
4	LABOUR TO RESPRAY REAR BUMPER, REAR PANEL INNER AND REAR LID.		\$ 2,800.00	\$ 2,800.00	? <i>640</i> ✓
5	LABOUR TO CARRY OUT DIAGNOSTIC CHECK		\$ 350.00	\$ 350.00	X <i>an</i>
				1280.00	
				5015.5	
				L/S - 4012.40 = 4000	
<i>En. Rial</i> <i>16/9/2022</i> <i>Lump sum repair</i> <i>After repair photos.</i> 3 DAYS					
LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:					
TOTAL				\$ 15,126.00	