



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22009097/Eqy3m4 Date: 03/10/2022 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6140Z	Veh. Inspected	SGZ 6505B	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/09/22/2031	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	15/09/2022	
2. Vehicle Particulars & Condition				
Make & Model	SUZUKI SWIFT	c.c	1490	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	JSAEZC21S00405717	Colour	ORANGE	
Odometer	201496 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	GOODRICH	4 mm	
L/H Front Tyre	185/65 R15	GOODRICH	4 mm	
R/H Rear Tyre	185/65 R15	GOODRICH	4 mm	
L/H Rear Tyre	185/65 R15	GOODRICH	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/09/2022	Inspection Date	19/09/2022	
Survey held at	AUTO WHEELS MOTORWORKS PTE LTD NO 1 BUKIT BATOK CRESCENT #02-40 WCEGA PLAZA SINGAPORE 658064			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	