



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
GREAT AMERICAN INSURANCE COMPANY 3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Ref: CS/GAI22009101/Gwy3m4 Date: 13/01/2023 Code: GAI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBK 6375Y	Veh. Inspected	SKG 1013P
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVC000004230	Excess (\$)	0.00
Assign From	SHERY WONG	Assign Date	15/09/2022
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ C180	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WDD2050402R175692	Colour	RED
Odometer	115468 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/50R17	CONTINENTAL	6 mm
L/H Front Tyre	225/50R17	CONTINENTAL	6 mm
R/H Rear Tyre	225/50R17	CONTINENTAL	6 mm
L/H Rear Tyre	225/50R17	CONTINENTAL	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	14/09/2022	Inspection Date	16/09/2022
Survey held at	TSR AUTOMOTIVE PTE LTD 160 SIN MING DRIVE #06-01 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	