

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Khong Lin Hui Lynn

Date: 21 Dec 2022

Preliminary Advice

Insured Vehicle No : SMM6238U

TP Vehicle No : SMZ1363E

Make : TOYOTA PRIUS

Date of Inspection : 15/09/2022

Inspection At : MY CAR CONSULTANT PTE LTD

Accident Date : 22/07/2022

Assignment Date : 15/09/2022

Est. Duration of Repair : 3 days

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,267.28
Revised Amount	:S\$	2,126.55
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,126.55

Lump Sum Repair	:S\$	1,700.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments : The above survey was conducted on a 'Without Prejudice' basis.

Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.