



Liu's Brother Auto Engineering Workshop

No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883

UEN No: 53291793J liusbros@gmail.com

Tel: 67411730

ESTIMATE

Name: MSIG Insurance (Singapore) Pte Ltd

Address: Motor Claims Department

4 Shenton Way #21-01

SGX Centre 2

Singapore 068807

Ref Date:

15/09/2022

Ref No:

GBF7493J220907

Vehicle No:

GBF7493J

Model / Make:

Nissan NV200 1.5 MT ABS

Airbag 2WD 6DR E5 W/RC

Item #	Damaged Area	Description	Unit Price	Qty	Estimation / Quotation	N / SN	Cost Of Repair
1	Rear Rh	Tailgate 1102.20 20/20ent	\$ 1,545.40	1	\$ 1,545.40	N	✓
2		Tailgate Hinge Lower 11	\$ 195.00	1	\$ 195.00	N	X
3		Tailgate Lock Upper 11	\$ 90.50	1	\$ 90.50	N	X
4		Tailgate Lock Lower 11	\$ 105.50	1	\$ 105.50	N	X
5		Tailgate Weatherstrip 11	\$ 82.60	1	\$ 82.60	N	X
6		Tailgate "dci" Emblem 11	\$ 70.70	1	\$ 70.70	N	✓
7		Tailgate "6 PAX" Sticker 11	\$ 15.00	1	\$ 15.00	SN	✓
8		Tailgate Windscreen Glass Sealant 11	\$ 50.00	1	\$ 50.00	SN	105/11
9		Tail Lamp 309.80 11	\$ 319.70	1	\$ 319.70	N	405/11
10		Body Panel (Fender) 11	\$ 1,891.60	1	\$ 1,891.60	N	X
11		Bumper Retainer 01 66.80 11	\$ 145.00	1	\$ 145.00	N	✓
12		Bumper Reflector 11	\$ 47.90	1	\$ 47.90	N	X
13	Rear	Bumper 488.90 11	\$ 624.80	1	\$ 624.80	N	✓
14		Bumper Clips 12 pcs 150f 11	\$ 6.50	12	\$ 78.00	N	305/11
15		Bumper Reverse Sensor 11	\$ 220.00	1	\$ 220.00	SN	2005/11
16		Bumper Sponge 11	\$ 88.90	1	\$ 88.90	N	✓
17		"Corporate" Advertisement & Artwork 11			\$ 220.00	SN	X 107
18		Remove & reinstall Tailgate Glass to facilitate repairs			\$ 120.00		100
19		To check all wiring & electrical component for proper function			\$ 60.00		20
20		Remove and refix rear tailgate components & mechanism			\$ 60.00		50
21		Remove and refix rear bumper reverse sensor			\$ 120.00		40
22		Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc			\$ 900.00		580
23		To putty & spray painting & including touch up paint on accident affected areas			\$ 700.00		550

Total Parts & Labour of estimate for damaged vehicle

\$ 7,750.60

Total amount in Lumpsum Basis for repaired vehicle

SDL

Not Authorized

16/9/22

2/5 2800

4 days

10/9/22

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed
- is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Liu's Bro Auto Engrg Wks

2-2124-3

102

19/11/87

280

1340

3831-87