


Section A - Accident Details

Registration Number	SHB1178J
Case Reference Number	TAX/09/22/2029
Registration Date	23/9/2021
Company Type	Strides Taxi Pte Ltd
Make	MORRISGARAGES
Model	MG5
Name of Driver	ABDUL RAHMAN BIN SHARIFF
Type of Accident	Side Swipe
Accident Date and Time	2/9/2022 5:00 PM
Accident Reported Date and Time	13/9/2022 11:10 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24116180
Special Instruction to ARC, if any	TP/ TOWED
Prepared Date and Time	13/9/2022 5:45 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$4,200.00	\$1,800.00
Total Spray Cost	\$2,590.00	\$1,470.00
Total Spare Part Cost	\$27,782.42	\$22,754.75
Total Other Cost	\$1,482.00	\$720.00
TOTAL COST	\$36,054.42	\$26,744.75 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	15.0	12.0
Prepared / Adjusted By	Boon Chew Tay	RASUL (LKK) / NTUC
ARC / Surveyor Sign Off Date	15/11/2022 1:27 PM	15/11/2022 1:04 PM
Signature		
Remarks	INITIAL 12 DAYS / SUP 3 DAYS / TOTAL 15 DAYS part by part / Before paint photo , After repair photo FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR RASUL / HP : 9001 0068. email: rasul@lkkauto.com	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2212-0090	Invoice Number	
Quotation Date	13.12.2022	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT CHASSIS RH	\$600.00	\$300.00
TO REPAIR FRONT PORTION	\$3,600.00	\$1,500.00
Total Labour	\$4,200.00	\$1,800.00

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRT MEMBER,RH	\$220.00	\$220.00
TO RESPRAY FRONT BUMPER	\$428.00	\$220.00
TO RESPRAY FRONT HOOD	\$428.00	\$220.00
TO RESPRAY FRONT FENDER RH	\$428.00	\$220.00
TO RESPRAY FRONT FENDER LH	\$428.00	\$220.00
TO RESPRAY FRT MEMBER,LH	\$230.00	\$150.00
TO RESPRAY FRONT DOOR LH	\$428.00	\$220.00
Total Spray Painting & Panel Beating	\$2,590.00	\$1,470.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE AND REFIT WIRE HARDESS	\$250.00	\$150.00
TOWING CHARGE	\$112.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$40.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$80.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK & RESET SYSTEM FUNCTION	\$350.00	\$150.00
ISOLATED OF (EV) (NET)	\$150.00	\$150.00
TO TOP UP A/C GAS	\$120.00	\$100.00
TO CONDUCT RADIATOR PRESSURE CHECK	\$120.00	\$50.00
Total Other Costs	\$1,482.00	\$720.00

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		10758052	CABLE ASM-HOOD PRIM LAT REL	1.00	\$9.75	10.00	\$8.78	Replace	Replace
		50004880-SEPP	BRACKET-F/FDR FRT LWR - LH	1.00	\$15.81	10.00	\$14.23	Replace	Replace
			NUMBER PLATE	1.00	\$35.00	0.00	\$35.00	Replace	Replace

√
√
√

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 30/12/2022

User ID : PohSuan

			NUMBER PLATE FRAME	1.00	\$25.00	0.00	\$25.00	Replace	Replace	√
		10236721-SEPP	HOOD ASM	1.00	\$2,407.29	10.00	\$2,166.56	Replace	Replace	√
		10574081-SEPP	HINGE ASM-HOOD - RH	0.00	\$54.81	0.00	\$0.00	Replace	Not Given	X
		10574080-SEPP	HINGE ASM-HOOD - LH	0.00	\$54.81	0.00	\$0.00	Replace	Not Given	X
		10321486	WEATHERSTRIP ASM-HOOD RR	1.00	\$20.80	10.00	\$18.72	Replace	Replace	√
		K7148511100	BUMPER-HOOD	4.00	\$6.00	10.00	\$21.60	Replace	Replace	√
		10328405	HOOD INSULATOR-F/CMPT	1.00	\$70.92	10.00	\$63.83	Replace	Replace	√
		91000573	HOOD INSULATOR CLIP-F/CMPT INSL	12.00	\$0.31	10.00	\$3.35	Replace	Replace	√
		10074727	PLUG-HOOD	2.00	\$0.42	10.00	\$0.76	Replace	Replace	√
		10806465	LATCH ASM-HOOD	1.00	\$80.70	10.00	\$72.63	Replace	Replace	√
		10236735-SEPP	FENDER ASM-FRT - L	1.00	\$379.81	10.00	\$341.83	Replace	Replace	√
		50004880-SEPP	BRACKET-F/FDR FRT LWR - LH	1.00	\$15.80	10.00	\$14.22	Replace	Replace	√
		10533649	INSULATOR ASM-F/FDR -LH	0.00	\$29.22	0.00	\$0.00	Replace	Check	X
		10516114	INSULATOR ASM-F/FDR MID - LH	0.00	\$8.94	0.00	\$0.00	Replace	Check	X
		10236736-SEPP	FENDER ASM-FRT-RH	1.00	\$379.81	100.00	\$0.00	Replace	Repair	R
		50004882-SEPP	BRACKET-F/FDR FRT LWR - RH	0.00	\$15.81	0.00	\$0.00	Replace	Not Given	X
		10533650	INSULATOR ASM-F/FDR-RH	0.00	\$29.22	0.00	\$0.00	Replace	Not Given	X
		10516113	INSULATOR ASM-F/FDR MID - RH	0.00	\$8.94	0.00	\$0.00	Replace	Not Given	X
		10169203-SEPP	DOOR ASM-FRT SI - LH	1.00	\$2,338.76	100.00	\$0.00	Replace	Repair	R
			STICKER STRIDES TAXI (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	√
		10879244	MODULE-FRT END	1.00	\$295.26	10.00	\$265.73	Replace	Replace	√
		10894738	BRACKET ASM-HDLP UPP - LH	1.00	\$22.57	10.00	\$20.31	Replace	Replace	√
		10894740	BRACKET ASM-HDLP UPP - RH	1.00	\$22.57	10.00	\$20.31	Replace	Replace	√
		10353833-SEPP	BAR ASM-DA PNL UPR CR - LH	1.00	\$198.22	100.00	\$0.00	Replace	Repair	R
		10892857	LINER ASM-FRT W/H - LH	1.00	\$125.22	10.00	\$112.70	Replace	Replace	√
		10825313	DEFLECTOR-U/B FRT	1.00	\$169.72	10.00	\$152.75	Replace	Replace	√
		10325882-SPRP	FASCIA-FRT BPR	1.00	\$721.66	10.00	\$649.49	Replace	Replace	√
		10361101	GRILLE-FRT BPR FASCIA LOWER	1.00	\$149.03	10.00	\$134.13	Replace	Replace	√
		10446164	FINISHER-FRT BPR LOWER - LH	0.00	\$20.38	0.00	\$0.00	Replace	Check	X
		10446163	FINISHER-FRT BPR - RH	0.00	\$20.38	0.00	\$0.00	Replace	Check	X
		10361099	COVER-FRT FOG LP - LH	1.00	\$40.25	10.00	\$36.23	Replace	Replace	√
		10361100	COVER-FRT FOG LP - RH	1.00	\$40.25	10.00	\$36.23	Replace	Replace	√
		10361097	FINISHER-FRT FOG LP CVR - LH	1.00	\$47.32	10.00	\$42.59	Replace	Replace	√
		10361098	FINISHER-FRT FOG LP CVR - RH	1.00	\$47.32	10.00	\$42.59	Replace	Replace	√
		10326366	BRACKET-FRT BPR FASCIA - LH	1.00	\$23.09	10.00	\$20.78	Replace	Replace	√
		10326368	BRACKET-FRT BPR FASCIA - RH	1.00	\$23.09	10.00	\$20.78	Replace	Replace	√
		10371562-SPRP	COVER-FRT BPR FASCIA TOWG	0.00	\$17.78	0.00	\$0.00	Replace	Not Given	X
		10361096	FINISHER-FRT BPR - RH	1.00	\$98.80	10.00	\$88.92	Replace	Replace	√
		10751682	SUPPORT-FRT BPR FASCIA UPR	0.00	\$172.33	0.00	\$0.00	Replace	Check	X
		90003382	BOLT/SCREW-FRT BPR FASCIA	21.00	\$0.15	10.00	\$2.84	Replace	Replace	√
		91000181	BOLT/SCREW-FRT BPR IMP BAR	5.00	\$0.73	10.00	\$3.29	Replace	Replace	√
		10137999	NUT-RAD GRL	4.00	\$2.18	10.00	\$7.85	Replace	Replace	√

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 30/12/2022

User ID : PohSuan

		90003382	BOLT/SCREW-FRT BPR FASCIA	4.00	\$0.15	10.00	\$0.54	Replace	Replace	√
		91000089	CLIP-FRT BPR FASCIA BRKT	2.00	\$1.95	10.00	\$3.51	Replace	Replace	√
		10954633	PANEL ASM-LEG CTHR	1.00	\$131.04	10.00	\$117.94	Replace	Replace	√
		10892798-SEPP	BAR ASM-FRT BPR IMP	1.00	\$624.00	10.00	\$561.60	Replace	Replace	√
		90004681	BOLT/SCREW-FRT BPR IMP BAR	10.00	\$1.66	10.00	\$14.94	Replace	Replace	√
		10751478	GRILLE ASM-RAD	1.00	\$978.02	10.00	\$880.22	Replace	Replace	√
		10872987	BRACKET-F/CMPT TR PLT	0.00	\$55.33	0.00	\$0.00	Replace	Not Given	X
		10737506	BRACKET-F/CMPT TR PLT	0.00	\$44.51	0.00	\$0.00	Replace	Not Given	X
		10737505	COVER-F/CMPT ORNA	1.00	\$217.67	10.00	\$195.90	Replace	Replace	√
		91000024	RIVET-F/CMPT ORNA CVR	10.00	\$1.25	10.00	\$11.25	Replace	Replace	√
		90003461	BOLT/SCREW-F/CMPT ORNA CVR	6.00	\$0.52	6.00	\$2.93	Replace	Replace	√
		10751567	HEADLAMP ASM -LH	1.00	\$1,098.86	10.00	\$988.97	Replace	Replace	√
		10751568	HEADLAMP ASM - RH	1.00	\$1,098.86	10.00	\$988.97	Replace	Replace	√
		11011337	SOCKET-CHRG	0.00	\$2,036.74	0.00	\$0.00	Replace	Check	X
		10413521	FAN ASM-ENG CLG	1.00	\$881.09	10.00	\$792.98	Replace	Replace	√
		10202935	INSULATOR-RAD UPR	0.00	\$10.92	0.00	\$0.00	Replace	Check	X
		10462845	RADIATOR ASM	1.00	\$547.87	10.00	\$493.08	Replace	Replace	√
			COOLANT	1.00	\$12.30	0.00	\$12.30	Replace	Replace	√
		10130431	INSULATOR-RAD LWR	0.00	\$3.95	0.00	\$0.00	Replace	Check	X
		10769602	CONDENSER ASM-A/C	1.00	\$516.78	10.00	\$465.10	Replace	Replace	√
		10455687	SHROUD ASM-RAD CLG - RH	0.00	\$14.77	0.00	\$0.00	Replace	Check	X
		10455704	SHROUD ASM-RAD CLG	0.00	\$12.79	0.00	\$0.00	Replace	Check	X
		10455705	SHROUD ASM-RAD CLG	0.00	\$12.79	0.00	\$0.00	Replace	Check	X
		10455706	SHROUD ASM-RAD CLG	0.00	\$14.77	0.00	\$0.00	Replace	Check	X
		10892859	LINER ASM-FRT W/H - RH	0.00	\$125.32	0.00	\$0.00	Replace	Check	X
Total					\$16,750.14		\$10,034.26			

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		24111499	COMPRESSOR ASM-A/C	1.00	\$6,220.81	10.00	\$5,598.73	Replace	Replace
		10574081-SEPP	HINGE ASM-HOOD - RH	1.00	\$54.81	10.00	\$49.33	Replace	Replace
		10574080-SEPP	HINGE ASM-HOOD - LH	1.00	\$54.81	10.00	\$49.33	Replace	Replace
		10446164	FINISHER-FRT BPR LOWER - LH	1.00	\$20.38	10.00	\$18.34	Replace	Replace
		10446163	FINISHER-FRT BPR - RH	1.00	\$20.38	10.00	\$18.34	Replace	Replace
		10371562-SPRP	COVER-FRT BPR FASCIA TOWG	1.00	\$17.78	10.00	\$16.00	Replace	Replace
		10751682	SUPPORT-FRT BPR FASCIA UPR	1.00	\$172.33	10.00	\$155.10	Replace	Replace
		10872987	BRACKET-F/CMPT TR PLT	1.00	\$55.33	10.00	\$49.80	Replace	Replace
		10737506	BRACKET-F/CMPT TR PLT	1.00	\$44.51	10.00	\$40.06	Replace	Replace
		11011337	SOCKET-CHRG	1.00	\$2,036.74	10.00	\$1,833.07	Replace	Replace
		10130431	INSULATOR-RAD LWR	1.00	\$3.95	10.00	\$3.56	Replace	Replace
		10892859	LINER ASM-FRT W/H-RH	1.00	\$125.32	10.00	\$112.79	Replace	Replace
		10753134	CABLE-BAT CHRG	1.00	\$153.72	10.00	\$138.35	Replace	Replace

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 30/12/2022

User ID : PohSuan

		10903093	HARNESS ASM-F/CMPT WRG (VCU 1 CONNECTOR)	1.00	\$4,846.10	10.00	\$4,361.49	Replace	Replace	√
		10782920	SPEAKER-PED ALERT	1.00	\$102.96	10.00	\$92.66	Replace	Replace	√
		10361095	FINISHER-FRT BPR - LH	1.00	\$98.80	10.00	\$88.92	Replace	Replace	√
		10996967	CONTAINER-WSWA SOLV	1.00	\$52.72	10.00	\$47.45	Replace	Replace	√
		10455687	SHROUD ASM-RAD CLG - RH	1.00	\$14.77	10.00	\$13.29	Replace	Replace	√
		10455706	SHROUD ASM-RAD CLG	1.00	\$14.77	10.00	\$13.29	Replace	Replace	√
		10175065	SENSOR ASM-AMB AIR TEMP	1.00	\$14.98	10.00	\$13.48	Replace	Replace	√
		10130431	INSULATOR-RAD LWR	2.00	\$3.95	10.00	\$7.11	Replace	Replace	√
Total					14,129.92		12,720.49			

22,754.75
+ 1800.00
+ 2190.00
26,744.75