



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022
255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

Customer:	CU0097089 / CHINA TAIPING	Document No:	SVO22044035
Chassis No:	MRHGM6660GP000483	Printed By:	IVANTEO
License No:	SLB4265Z	Order Date:	3. October 2022
Mileage:	139121	Order Time:	11:08:55 AM
Engine No:	L15Z12722055	Service Advisor:	IVAN TEO BOON KIAT

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:14926) OWNER: LIM HEONG KHAI OWNER INSURER: INCOME INSURANCE ACC DATE: 13/09/2022 SURVEYED BY: DATE: REF NO: TP INSURER: CHINA TAIPING TP VEH: SKA7814L SUPPLEMENTARY PART						
68500-T9A-T30ZZ	LID COMPTRUNK	1	528.40	25	396.30	27.74	424.04
74851-T2A-003	LOCK ASSYTRUNK	1	106.80	25	80.10	5.61	85.71
74865-T9A-T01	WEATHERSTRIPTRUNK LID	1	85.10	25	63.82	4.47	68.29
75701-T9A-000	EMBLEM H	1	13.00	25	9.75	0.68	10.43
75722-T9A-T00	EMBLEMRR.CITY	1	13.40	25	10.05	0.70	10.75
75725-T9A-T00	EMBLEMRR.I-VTEC	1	14.00	25	10.50	0.74	11.24
91512-SR3-004	CLIP TUBULAR	2	2.40	25	3.60	0.25	3.85
74890-T9A-T11	GARNISH ASSYRR.LICENSE	1	73.70	25	55.27	3.87	59.14
71501-T9A-T00ZZ	FACERR.BUMPER	1	463.70	25	347.77	24.34	372.11
71593-T9A-J00	SPACER R.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71598-T9A-J00	SPACERL.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIP,BUMPER	4	2.30	25	6.90	0.48	7.38
66100-T9A-T50ZZ	PANEL COMPRR.	1	385.00	25	288.75	20.21	308.96
84640-T9A-T01ZA	LINING ASSYRR.PANEL	1	66.60	25	49.95	3.50	53.45
84521-T9A-T10	LID COMPSPARE TIRE	1	52.00	25	39.00	2.73	41.73
	SUM PARTS:				1,379.00	96.52	1,475.52
BOSUN		1	50.00		50.00	3.50	53.50
	SUNDRIES						
BML02I		1	250.00		250.00	17.50	267.50
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)						
BA02R		1	250.00		250.00	17.50	267.50
	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)						
BKTRK		1	325.00		325.00	22.75	347.75
	STRAIGHTEN ALIGN TRUNK LID.						
BC012R		1	580.00		580.00	40.60	620.60
	RESET VEHICLE SMART ENTRY SYSTEM						
BC011R		1	580.00		580.00	40.60	620.60
	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA						
BKRP02S	0671	1	3,250.00		3,250.00	227.50	3,477.50
	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.						
BP05R	1847	1	1,560.00		1,560.00	109.20	1,669.20



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022
255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

Customer:	CU0097089 / CHINA TAIPING	Document No:	SVO22044035
Chassis No:	MRHGM6660GP000483	Printed By:	IVANTEO
License No:	SLB4265Z	Order Date:	3. October 2022
Mileage:	139121	Order Time:	11:08:55 AM
Engine No:	L15Z12722055	Service Advisor:	IVAN TEO BOON KIAT

SPRAY PAINTING ON REPAIRED OR
REPLACED AREAS.(5P)

SUM LABOUR:	6,845.00	479.15	7,324.15
TOTAL SGD	8,224.00	575.67	8,799.67

Total Payable (SGD) 8,799.67

GST Amount is calculated from individual line(s)