12/1/22, 2:27 PM Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/MSG21013092/GVY3M4-1

01/12/2022 Date:

**REFERENCE** 

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 28758454

**Claimant Vehicle** FBK7990P Insured Vehicle No: GBD8605H No:

Date of Loss: 21/03/2019 Nature of Claim: TP Claim No: 588499

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: **FBK7990P** 

Make & Model: KAWASAKI ZG1400C. 1.4 ZXT40AE073607 Engine No: Reg. Date: 31/01/2013 (Man. Year: 2012) Chassis No: JKBZGT40CCA020793

Colour: Odometer: 80909 km Grey

**Engine Capacity:** 1352 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price** 

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 120/70 ZR17 Rear Tyre Size: 190/55 ZR17 Front Left Side: Rear Left Side: Bridgestone 6 mm Bridgestone 6 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		12,644.00	2,466.50	10,177.50	80.49
Miscellaneous Items		0.00	0.00	0.00	
Labour		600.00	300.00	300.00	50.00
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
N	lett Amount (S\$)	13,244.00	2,766.50	10.477.50	79.11

**INSPECTION** 

Date of Assignment: 24/12/2021

M2 GARAGE PTE LTD

61 WOODLANDS INDUSTRIAL PARK E9 Date Inspected: 19/09/2022 Inspected At: #01-17 E9 PREMIUM

SINGAPORE 757047

Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG **VERON CHEN** Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### **REPAIR DETAILS**

Reference

Part Source: (Last Synchronised: 01 Dec 2022)

Parts: N/A KAWASAKI ZG1400C 1.4 (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBK7990P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER , INNER , LH	Serviceable	180.00 F	*- FL
2	1		*BRACKET, MIRROR	Replaced	450.00 F	*265.00 FL
3	1		*BRACKET , COWLING	Serviceable	480.00 F	*- FL
4	1		*PIPE-FORK INNER , RH	Serviceable	1,400.00 F	*- FL
5	1		*PIPE-FORK INNER , LH	Serviceable	1,400.00 F	*- FL
6	2		*SEAL-OIL , FORK OUTER TUBE	Serviceable	190.00 F	*- FL
7	1		*HOLDER-FORK UNDER	Serviceable	834.00 F	*- FL
8	1		*COVER , SIDE BAG , RH	Not fitted	700.00 F	*- FL
9	1		*COVER , SIDE BAG , LH	Not fitted	700.00 F	*- FL
10	2		*COVER , SIDE BAG , LID	Not fitted	700.00 F	*- FL
11	1		*BODY END-MUFFLER, RR	Not fitted	250.00 F	*- FL
12	1		*BODY END-MUFFLER, FR	Not fitted	300.00 F	*- FL
13	1		*CLAMP, 64.5MM	Replaced	70.00 F	*70.00 FL
14	1		*HOLDER-HANDLE , RH (SILVER)	Serviceable	160.00 F	*- FL
15	1		*HANDLE , RH	Replaced	250.00 F	*250.00 FL
16	1		*HOLDER-HANDLE , LH (SILVER)	Serviceable	160.00 F	*- FL
17	1		*HANDLE , LH	Serviceable	250.00 F	*- FL
18	1		*GRIP-ASSY , THROTTLE , HEATE	Serviceable	280.00 F	*- FL
19	1		*GRIP-LH , HEATER	Serviceable	280.00 F	*- FL
20	1		*ENGINE PROTECT GUARD (2Pieces)	Replaced (1Piece Only)	560.00 F	*280.00 FL
21	1		*BAR END BALANCE (2Pieces)	Replaced (1Piece Only)	160.00 F	*80.00 FL
22	2		*SEAL , FORK OUTER TUBE (SN)	Replaced	190.00 FS	*76.00 FS
23	2		*FORK OIL (SN)	Replaced	140.00 FS	*40.00 FS
24	1		*BODY-COMP-MUFFLE (SN)	Replaced	2,560.00 FS	*1,500.00 FS
F=Fra	nchise	part. S=SpcN	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	12,644.00	2,561.00
	- List Item Discount on L Items 0.00/10.00% (S\$)			0.00	94.50	
				Total Parts (S\$)	12,644.00	2,466.50
			Report was unsubm	nitted during this print-out.		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	LABOUR	New	600.00	300.00
		Gross Labour Cost (S\$)	600.00	300.00
		Report was unsubmitted during this print-out.		

< END OF ESTIMATES >