

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
|---|---|---|----------------|-------|---------------------|--|
| | MSIG INSURANCE | (S) PTE LTD | | Ref: | CS/MSG22009169/AGnc | |
| | 4 SHENTON WAY SGX CENTRE 2 SI | #21-01 NGAPORE 068807 | | Date: | 19/09/2022 | |
| | | | | Code: | MSG | |
| 1. | 1. Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | SGN 3547S | Veh. Inspected | ı | SJZ 9281R | |
| | Policy No. | 1002176805 | Coverage (\$) | | 0.00 | |
| | Claim No. | 285312 | Excess (\$) | | 0.00 | |
| | Assign From | | Assign Date | | 19/09/2022 | |
| 2. Vehicle Particulars & Condition | | | | | | |
| | Make & Model | | c.c | | 0 | |
| | Engine No. | HIDDEN | Year of Reg. | | | |
| | Chassis No. | | Colour | | | |
| | Odometer - | | Steering | | | |
| | Brakes | | Modification | | | |
| | General | | | | | |
| 3. Conditions of Tyres | | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | | | | mm | |
| | L/H Front Tyre | | | | mm | |
| | R/H Rear Tyre | | | | mm | |
| | L/H Rear Tyre | | | | mm | |
| 4. | Description of Damages | | | | | |
| | | | | | | |
| 5. | | Information | | | | |
| | Accident Date | 16/09/2022 | Inspection Dat | е | 19/09/2022 | |
| | Survey held at | vey held at MIRAGE MOTORWERKZ PTE LTD | | | | |
| | | 10 KAKI BUKIT ROAD 2 #01-29 FIRST EAST CENTRE SINGAPORE 417868 | | | | |
| 5a. Rer | | | emarks | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |