



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:GARNET		Ref: CC4/ASM22009177/Upa3q2 Date: 07/02/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 3522A	Veh. Inspected	FBN 9168T
Policy No.	P2465679	Coverage (\$)	0.00
Claim No.	S2M04B04	Excess (\$)	0.00
Assign From		Assign Date	16/09/2022
2. Vehicle Particulars & Condition			
Make & Model	YAMAHA AEROX GDR 155	c.c	155
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	MH3SG4610JJ171884	Colour	PURPLE / SILVER
Odometer	60522 KM	Steering	AFFECTED
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	110-80-14	MAXXIS	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	140/70-14	MAXXIS	6 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION & N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	13/09/2022	Inspection Date	19/09/2022
Survey held at	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	