

ASS. REC. BY: Marcus

REF:

CC4/ASM 22009177/UP93

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

\$9k.

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐

Preli. Report

☐

Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, Si

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

police report DOA Different.
have video of folder April 2002
30/1/23 1/5 #3100 inbound air 700
reject case.

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Email: erofia@singnet.com.sg

Name : Qusyairi Haziq Bin Halil
(81210511)

Accident Date : 13-Sep-22

Vehicle No : FBN9168T (COE271228)

Vehicle Model : Yamaha Aerox
GDR155CVT

Estimated Repair Costs

Qty	Description List Items	Amount S(\$)
1	Front fender (matt) 520	152 \$ 175.00
1	Front fork assy 320/120	780 \$ 980.00
1	Fork under bracket 250	\$ 190.00
1	Front sport rim 17	\$ 550.00
1	Front brake disc 17	\$ 180.00
1	Front rim shaft 17	\$ 52.00
1	Front rim bearing 17	\$ 48.00
1	Front side cover (1 set) - matt 150	\$ 260.00
1	Front side inner cover - matt 150	\$ 210.00
1	Front lower cover 148	\$ 195.00
1	Fuel tank cover 105	\$ 105.00
1	Headlamp (LED) 699	\$ 980.00
1	Side mirror (1 set) 60	\$ 120.00
1	Handle-bar 165	\$ 165.00
1	Handle-bar balancer (1 set) 30	\$ 115.00
1	Hand grip (1 set) 60	\$ 60.00
2	Brake lever 55	\$ 110.00
2	Footstep panel 138	\$ 510.00
2	Footstep panel lower cover 135	\$ 340.00
1	Exhaust assy 17	\$ 680.00
1	Exhaust protector 17	\$ 48.00
1	Fairing cover (1 set) 900	\$ 1,450.00
1	Rear footrest 180	\$ 180.00
		\$ 7,703.00
	Less 10%	\$ 770.30
		\$ 6,932.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Email: erofia@singnet.com.sg

Name : Qusyairi Haziq Bin Halil
(81210511)

Accident Date : 13-Sep-22

Vehicle No : FBN9168T (COE271228)

Vehicle Model : Yamaha Aerox
GDR155CVT

Estimated Repair Costs

Special Net Items

1	Number plate (1 set)	1 ✓	\$	38.00	X
2	Fork oils	1 ✓	\$	30.00	X
2	Fork oil seals	1 ✓	\$	56.00	X
1	Steering cone (1 set)	1 ✓	\$	68 120.00	✓
1	Rear box	1 ✓	\$	480.00	X
1	Rear box bracket	1 ✓	\$	180.00	X
1	Sticker (1 set)	1 ✓	\$	120.00	X
1	"AEROX" emblemen	1 ✓	\$	60.00	X
			\$	1,084.00	

S/No. Labour


1	To provide towing (LOD) S\$40.00	\$	-	
2	To provide wiring and reset headlamp focusing	\$	11 80.00	X
3	To repair body frame	\$	11 380.00	X
4	To provide labour	\$	450.00	300
		\$	<u>910.00</u>	

Grand Total

\$ 8,926.70

Singapore Dollars: Eight Thousand Nine Hundred Twenty-Six and Cents: Seventy only

3899.3


EROFIA MOTOR TRADING PTE LTD