

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/TP/0813/2022/EQ  
**DATE** : 20-Sep-22  
**WIP** : 42524

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 23/09/2022**  
**YOUR INSURED VEH NO : SKZ 8500 D**

**AIG Asia Pacific Insurance Pte Ltd**  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120  
Attn: Motor Claims Dept

**OWNER'S NAME** : MR ADITYA BHARGAVA  
**ADDRESS** : 2A CORNWALL GARDENS  
SINGAPORE 269678  
  
**TELEPHONE** : HP +65 90677250  
**TYPE OF CLAIM** : THIRD PARTY CLAIM  
**POLICY NO** : P10674813R00  
**VEHICLE NO** : SMR 3702 P  
**MODEL CODE** : AUDI A5 SPORTBACK 2.0 TFS  
**MODEL YEAR** : 31/12/2019  
**ENGINE NO** : CVK 088187  
**CHASSIS NO** : WAUZZZF54KA079221  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 15-Sep-22  
**PLACE OF ACCIDENT** : LOEWEN ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMR 3702 P**

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 /	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00 250	
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND HEADLIGHT. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. \$500 X 2	\$ 2,400.00 1000	
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER. \$500 X 2	\$ 1,900.00 1100	
5	TO CARRY OUT DISGNOSTIC CHECK.	S/N \$ 192.00 /	
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 5,372.00</b>	

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 3702 P**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER / BR	1	\$ 2,493.00	✓ \$1994.40
2	FRONT BUMPER FIXING PARTS X NN	1	\$ 425.00	
3	FRONT BUMPER GRILLE - CENTER ? X NN	1	\$ 219.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE ? BR	1	\$ 254.00	✓ \$203.20
5	FRONT BUMPER SPOILER ? X NN	1	\$ 599.00	
6	FRONT BUMPER AIR GUIDE - RH ? X NN	1	\$ 72.00	
7	FRONT BUMPER AIR GUIDE GRILLE - RH / MS	1	\$ 529.00	✓ \$423.20
8	RADIATOR GRILLE / CN	1	\$ 2,576.00	✓ \$2,060.80
9	FRONT PARKING AID SENSOR SUPPORT - LH / RH ? X NN	2	\$ 116.00	
10	FRONT PARKING AID SENSOR - OUTER ? X NN	1	\$ 266.00	
11	FRONT PARKING AID SEAL RING / REC	4	\$ 10.00	
12	FRONT BUMPER FOAM FILLER PIECE ? X NN	1	\$ 139.00	
13	FRONT BUMPER REINFORCEMENT BEAM ? X NN	1	\$ 899.00	
14	FRONT WHEEL SPOILER - RH ? BR	1	\$ 82.00	✓ \$65.12
15	FRONT SPOILER - RH ? CRU	1	\$ 40.00	✓ \$32.00
16	FRONT FENDER - RH / ON	1	\$ 1,189.00	✓ \$951.20
17	FRONT FENDER ATTACHMENT PARTS X NN	1	\$ 55.00	
18	FRONT FENDER CLOSING ELEMENT - RH ? BT	1	\$ 83.00	✓ \$65.84
19	FRONT FENDER BRACKET - RH ? BT	1	\$ 65.00	✓ \$32.72
20	FRONT FENDER BRACKET - LH / RH ? X NN	2	\$ 79.00	
<b>SUB TOTAL SPARE PARTS</b>		<b>:</b>	<b>\$ 10,190.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 3702 P**

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	FRONT FENDER BRACE - RH <i>7</i> BT	1	\$	132.00 ✓	\$105.20
22	FRONT FENDER RIVET <i>MC</i>	5	\$	19.00 ✓	\$15.20
23	FRONT FENDER LEDGE COVER - RH SHORT <i>1</i> <i>MC</i>	1	\$	18.00 ✓	\$13.92
24	FRONT FENDER LEDGE COVER - RH LONG <i>1</i> <i>MC</i>	1	\$	40.00 ✓	\$31.44
25	FRONT WHEEL HOUSING LINER - RH <i>1</i> CRU	1	\$	299.00 ✓	\$238.80
26	FRONT BUMPER GUIDE SECTION - RH <i>1</i> BR	1	\$	41.00 ✓	\$32.24
27	FRONT FENDER STONE CHIP GUARD <i>1</i> X NN	1	\$	57.00	
28	FRONT FENDER CHROME TRIM - RH <i>1</i> <i>MC</i>	1	\$	171.00 ✓	\$136.40
29	HEADLIGHT - RH <i>1</i> <i>CU</i>	1	\$	8,416.00 ✓	\$6,732.80
30	FRONT NUMBER PLATE <i>1</i> <i>MC</i>	S/N	\$	60.00 ✓	\$60.00
31	SUNDRIES <i>1</i> NEC		\$	300.00 20.80 ✓	
<b>TOTAL SPARE PARTS</b>		:	\$	<b>19,743.00</b>	
<b>TOTAL LABOUR CHARGES</b>		:	\$	<b>5,372.00</b>	
<b>GRAND TOTAL</b>		:	\$	<b>25,115.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME  
SURVEYED DATE  
AUTHORISED DATE  
EXCESS COST  
LIABILITY  
REMARKS

:  
:  
:  
:  
:  
:

Steve CLKKJ  
23/9/22, 3.00pm

00-N1 AL  
Excess?  
PJP

My BL 4  
5.15

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT