

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0813/2022/EQ
DATE : 20-Sep-22
WIP : 42524

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 23/09/2022

YOUR INSURED VEH NO : SKZ 8500 D

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR ADITYA BHARGAVA
ADDRESS : 2A CORNWALL GARDENS
SINGAPORE 269678

TELEPHONE : HP +65 90677250
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : P10674813R00
VEHICLE NO : **SMR 3702 P**
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFS
MODEL YEAR : 31/12/2019
ENGINE NO : CVK 088187
CHASSIS NO : WAUZZZF54KA079221
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 15-Sep-22
PLACE OF ACCIDENT : LOEWEN ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMR 3702 P

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND HEADLIGHT. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,400.00	
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$	1,900.00	
5	TO CARRY OUT DISGNOSTIC CHECK.	S/N \$	192.00	
TOTAL LABOUR CHARGES		:	\$ 5,372.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 3702 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,493.00	
2	FRONT BUMPER FIXING PARTS	1	\$ 425.00	
3	FRONT BUMPER GRILLE - CENTER	1	\$ 219.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 254.00	
5	FRONT BUMPER SPOILER	1	\$ 599.00	
6	FRONT BUMPER AIR GUIDE - RH	1	\$ 72.00	
7	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 529.00	
8	RADIATOR GRILLE	1	\$ 2,576.00	
9	FRONT PARKING AID SENSOR SUPPORT - LH / RH	2	\$ 116.00	
10	FRONT PARKING AID SENSOR - OUTER	1	\$ 266.00	
11	FRONT PARKING AID SEAL RING	4	\$ 10.00	
12	FRONT BUMPER FOAM FILLER PIECE	1	\$ 139.00	
13	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 899.00	
14	FRONT WHEEL SPOILER - RH	1	\$ 82.00	
15	FRONT SPOILER - RH	1	\$ 40.00	
16	FRONT FENDER - RH	1	\$ 1,189.00	
17	FRONT FENDER ATTACHMENT PARTS	1	\$ 55.00	
18	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 83.00	
19	FRONT FENDER BRACKET - RH	1	\$ 65.00	
20	FRONT FENDER BRACKET - LH / RH	2	\$ 79.00	
SUB TOTAL SPARE PARTS		:	\$ 10,190.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 3702 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER BRACE - RH	1	\$ 132.00	
22	FRONT FENDER RIVET	5	\$ 19.00	
23	FRONT FENDER LEDGE COVER - RH SHORT	1	\$ 18.00	
24	FRONT FENDER LEDGE COVER - RH LONG	1	\$ 40.00	
25	FRONT WHEEL HOUSING LINER - RH	1	\$ 299.00	
26	FRONT BUMPER GUIDE SECTION - RH	1	\$ 41.00	
27	FRONT FENDER STONE CHIP GUARD	1	\$ 57.00	
28	FRONT FENDER CHROME TRIM - RH	1	\$ 171.00	
29	HEADLIGHT - RH	1	\$ 8,416.00	
30	FRONT NUMBER PLATE	S/N	\$ 60.00	
31	SUNDRIES		\$ 300.00	
TOTAL SPARE PARTS		:	\$ 19,743.00	
TOTAL LABOUR CHARGES		:	\$ 5,372.00	
GRAND TOTAL		:	\$ 25,115.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT