

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/ASM22009188/Gnce2 AXA INSURANCE PTE LTD Ref: 8 SHENTON WAY #24-01 AXA TOWER Date: 29/09/2022 SINGAPORE 068811 ATTN: KITTY TEO Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **SHB 4316H** Veh. Inspected SNB 3631H Policy No. VFX/P2419138 Coverage (\$) 0.00 Claim No. S2M04B72 Excess (\$) 0.00 KITTY TEO **Assign Date** 19/09/2022 Assign From **Vehicle Particulars & Condition** 2. TOYOTA SIENTA 7-SEATER 1496 Make & Model C.C 1.5G Engine No. **HIDDEN** Year of Reg. 2021 Chassis No. NSP1707212234 Colour **BLUE** 53305 KM IN ORDER Odometer Steering **IN ORDER** SPORTS RIM **Brakes** Modification GOOD General **Conditions of Tyres** 3. Size Make **Balance** 185/65 R15 PETLAS 6 mm R/H Front Tyre PETLAS L/H Front Tyre 185/65 R15 6 mm R/H Rear Tyre 185/65 R15 **PETLAS** 6 mm 185/65 R15 **PETLAS** L/H Rear Tyre 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. **General Information** 5. **Accident Date** 16/09/2022 **Inspect Date / Time** 20/09/2022 (04:30 PM) 1 KAKI BUKIT AVE 6 #02-25 S (417883) Survey held at AF MOTORWORKZ PTE LTD Repairer 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000 5b. **Estimate Days of Repair**

Report Ref No. CS3/ASM22009188/Gnce2

Inspected By

ESTIMATED NORMAL PERIOD FOR REPAIR:

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

5 Working Days

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.