

ASS. REC. BY: fern

REF:

CS/ICS 22009225/Rvy3

1854

ASSIGNMENT

Lot XRAY: 2023/044

From: _____ Date: _____

Estimated Cost: _____

☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MVTo Inspect Vehicle No: SKD 86582at Workshop m/s ZHONG CHENGof 60, JLN LAM HUAN #04-53Insured: EICS

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: T6A

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☒
N/S	O/S
☐	☐

Bal. or Market Value: 11K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKD86582 Yr Regn: 2008 / JunType: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or _____

Make: HONDA CROSSROAD 1.8A c.c. 1799Colour: GREY A/C: ☒ Insured / ☐ Std / ☐ NI / ☐ NASp. Reading: 185031 T/Radio: ☒ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: _____

C/No: RT11007454Gen. Cond: Good / ☒ Fair / ☐ Poor / ☐ BurntSteering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: Nil / ☒ S/Rim / ☐ STD A/Rim orTyre Size: F: 225/55R17

R: _____

☒ BS / ☐ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /

TOYO / YOKO or _____

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 10/09/22

Survey held at

Des. of Damages ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 8K

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Rep. Form: _____

Lump Sum / L.B.I. (\$)

Zhong Cheng Enterprise Pte Ltd - Woodlands (Co.Reg.No:201611525M)
BLK 6 WOODLANDS ROAD, 399J YEW TEE INDUSTRIAL ESTATE
Singapore 678008
Tel: 67694686 Email: zhongchengauto@gmail.com

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	MPC21P00262200	Date of Loss:	10/09/2022
Vehicle Reg. No.:	SKD8658Z	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LOW LE MING		
Driver:	LOW LE MING		

Make/Model:	HONDA CROSSROAD, 1.8 (A)	Vehicle Reg. Date:	20/06/2008
Vehicle Colour:	Grey		
Engine No:	R18A3010092	Chassis No:	RT11007494
Odometer:	185031 KM		

Paint Type:

Total Loss? **NO**

Est. Duration of Repair (day) 4

Present Location: **ZHONG CHENG ENTERPRISE PTE LTD - WOODLANDS (HQ)**

COST OF CLAIMS

	Amount
Parts	10,679.90
Miscellaneous Items	782.13
Labour	1,710.00
Paintwork Labour	800.00
Towing	0.00
Nett Amount (S\$)	13,972.03

This claim is handled by: TAN SINI

Generated using *Merimen e-Claims Internet Estimation & Adjusting System*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 Sep 2022)
Parts: M1-SUV HONDA CROSSROAD 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Zhong Cheng Enterprise Pte Ltd - Woodlands/SKD8658Z/16/09/2022 18:05
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		Air-cond condenser <i>bt</i>	0.00	0.00	*580.00 F
2	1		Bonnet <i>bt</i>	0.00	0.00	*560.00 F
3	1		Bonnet lock <i>bt</i>	0.00	0.00	*80.00 F
4	1		Bumper air grille center, front <i>CA</i>	0.00	0.00	*320.00 F
5	1		Bumper bracket LH, front <i>Rec</i>	0.00	0.00	*40.00 F
6	1		Bumper bracket RH, front <i>Rec</i>	0.00	0.00	*40.00 F
7	1		Bumper reinforcement, front <i>bt</i>	0.00	0.00	*220.00 F
8	1		Bumper, front <i>bt</i>	0.00	0.00	*800.00 F
9	1		Fender bracket LH, front <i>X</i>	0.00	0.00	*12.00 F
10	1		Fender bracket RH, front <i>X</i>	0.00	0.00	*12.00 F
11	1		Fender LH, front <i>X</i>	0.00	0.00	*500.00 F
12	1		Fender RH, front <i>X</i>	0.00	0.00	*500.00 F
13	1		Headlamp LH <i>CA</i>	0.00	0.00	*740.00 F
14	1		Headlamp RH <i>CA</i>	0.00	0.00	*740.00 F
15	1		Panel, front <i>bt</i>	0.00	0.00	*650.00 F
16	1		Radiator <i>bt</i>	0.00	0.00	*900.00 F
17	1		W/screen glass moulding upper, front <i>bt</i>	0.00	0.00	*1,100.00 F
18	1		W/screen glass, front <i>CA</i>	0.00	0.00	*95.00 F
19	1		*carplate & housing <i>bt</i>	0.00	0.00	*60.00 F <i>35</i>
20	1		*front grille Honda logo emblem <i>bt</i>	0.00	0.00	*50.00 F
21	1		*radiator cowling <i>?</i>	0.00	0.00	*280.00 F
22	1		*AIR BAG CONTROL MODULE <i>ACT</i>	0.00	0.00	*550.00 F
23	1		*AIR BAG ASSY-PASSENGER <i>ACT</i>	0.00	0.00	*880.00 F

F=Franchise part.

Sub Total (\$\$)	9,709.00
+ Margin on L,N Items 10.00% (\$\$)	970.90
Total Parts (\$\$)	10,679.90

Zhong Cheng Enterprise Pte Ltd - Woodlands/SKD8658Z/16/09/2022 18:05. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Miscellaneous Items			Amount
1	1	aircon gas <i>MC /</i>	
2	1	gst <i>X</i>	30.00
3	1	top up coolant <i>MC /</i>	679.63
4	1	Windscreen sealant, front <i>MC /</i>	30.00
			42.50

Sub Total (S\$) 782.13

Estimates on Labour

No Particulars

Paintwork Labour		Lab.Type	Amount
1	spray paint & polish	New	800.00 600
Labour Items			
2	panel beating /dismantle/refix front portions	New	800.00 600
3	dismantle/refix airbag and dashboard	New	450.00 200
4	radiator & condenser fixing	New	160.00 100
5	remove fault code	New	200.00 100
6	dismantle & refix windscreen	New	100.00

Gross Labour Cost (S\$) 2,510.00

Zhong Cheng Enterprise Pte Ltd - Woodlands/SKD8658Z/16/09/2022 18:05. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

RASUL

Hp 90010068

8 7 days

L/S

20/09/22 @ 1645

EXCESS: TBA

REVERT

Resurvey after repair

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	185G
Vehicle No.:	SKD8658Z
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Sep 2022
Vehicle Make:	HONDA
Vehicle Model:	CROSSROAD 1.8 A
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	R18A3010092
Chassis No.:	RT11007494
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$19,243.00
Original Registration Date:	20 Jun 2008
First Registration Date:	20 Jun 2008
Transfer Count:	4
Actual ARF Paid:	\$19,243.00
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	31 May 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$19,356.00
COE Rebate Amount:	\$2,684.00
Total Rebate Amount:	\$2,684.00

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 21 Sep 2022

OK

Honda Crossroad 1.8A (COE till 08/2023)

Overview

[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

Price	\$14,600		
Depreciation ⓘ	\$16,150 /yr	Reg Date	18-Aug-2008 (10mths 27days COE left)
Mileage	143,000 km (10.1k /yr)	Manufactured ⓘ	2008
Road Tax ⓘ	\$1,467 /yr	Transmission	Auto
Dereg Value ⓘ	\$3,164 as of today (change)	OMV ⓘ	\$20,209
COE ⓘ	\$17,496	ARF ⓘ	\$20,209
Engine Cap	1,799 cc	Power	103.0 kW (138 bhp)
Curb Weight ⓘ	1,410 kg	No. of Owners ⓘ	3
Type of Vehicle	SUV		