

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wen Yao

Date: 06 Dec 2022

Preliminary Advice

Insured Vehicle No	: FBR2989R	Accident Date	: 17/09/2022
TP Vehicle No	: SLN8385X	Assignment Date	: 20/09/2022
Make	: TOYOTA PRIUS HYBRID	Est. Duration of Repair	: 5
Date of Inspection	: 20/09/2022		
Inspection At	: AUTOWORX PTE LTD (HQ) 10 ANG MO KIO INDUSTRIAL PARK 2A, #05-01 AMK AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,940.20
Revised Amount	:S\$	4,677.00
Check Items (Estimated)	:S\$	2,869.38
Total	:S\$	7,546.38

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- () Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.