

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 64528211 FAX: 64517420

ESTIMATE

MCQUEEN RENTALS PTE LTD
c/o 46 Lenton Plain
Singapore 786548

Not Notified
11 May 8 4550h
Recovery After Paint
5 days

Date : 20/9/2022

QUANTITY	PARTICULARS	AMOUNT (\$)
RE : TOYOTA PRIUS HYBRID / SLN 8385 X		
1 pc	Front fender	B ₁ 766.50
1 pc	Front fender emblem "HYBRID"	m 76.80
1 pc	Front fender dust cover <i>188.40</i>	CM 264.30
8 pc	Front fender dust cover clip @ 3.60	m 28.80
1 pc	Front bumper <i>593.10</i>	Bu / CM 967.80
1 pc	Front bumper side retainer	D ₁ 76.40
1 pc	Front head lamp	W 2,165.40
1 pc	Alloy rim <i>1355.10</i>	Bu 690.00
1 pc	Front knuckle arm	B ₁ 565.40
1 pc	Front wheel bearing	m 346.50
1 pc	Front shock absorber <i>460.00</i>	B ₁ 567.10
1 pc	Front lower arm	D ₁ 367.30
1 pc	Front steering tie rod	m 116.50
1 pc	Front steering tie rod end	m 162.70
sub-total		7,131.50
less 20% <i>25%</i>		1,426.30
sub-total		5,705.20

balance brought forward.	5,705.20
To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.	400/ 1,000.00
To check wiring system.	20/ 60.00
To apply putty & spray painting on affected areas.	400/ 800.00
To change the alloy rim.	20/ 40.00
To checke the wheel alignment.	60/ 85.00
To change the front RH under carriage	200/ 250.00
total	7,940.20

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

MCQUEEN RENTALS PTE LTD
c/o 46 Lenton Plain
Singapore 786548

Date: 20/10/2022

QUANTITY	PARTICULARS	AMOUNT (\$)
RE: TOYOTA PRIUS HYBRID / SLN 8385 X/SUPPLEMENTARY		
1 pc	Front lower arm ball joint	196.40 ✓
1 pc	Front anti roll bar linkage	188.50 X
1 pc	Front bumper upper reinforcement	651.40 Xnn
1 pc	Front bumper sponge absorber	546.30 ✓
1 pc	Front bumper fog lamp	667.10 ✓
1 pc	Front bumper lower reinforcement	540.00 X
1 pc	Front bumper lower reinforcement bracket	295.00 X
1 pc	Front bumper lower reinforcement pad	441.00 X
1 pc	Windscreen wiper washer tank	394.30 ✓
1 pc	Side mirror assy	679.50 X
Sub-total		4,599.50
Less 25%		1,149.88
Sub-total		3,449.63
To remove & replace front wheel bearing		80.00 201-
Total:		3,529.63