

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	ALLIANZ INSURAN	ICE SINGAPORE PTE LTD		Ref:	CS/AIS22009232/Uqy3	
	79 ROBINSON RO #09-01 SINGAPOR			Date:	20/09/2022	
				Code:	AIS	
1.	. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	GBK 5554D	Veh. Inspected		SGZ 9555L	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	2022 22006806FR	Excess (\$)		0.00	
	Assign From	SHANTI	Assign Date		20/09/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	Steering				
	Brakes	Modification				
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5.	5. General Information					
	Accident Date	14/09/2022	Inspection Date	е	20/09/2022	
	Survey held at	1 Kaki Bukit Road Ave 6 #02-47 AutoBay @ KB				
	Repairer	JC MOTORS PTE LTD				
5a. Remarks						
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					