

AGS. REC BY: T. J. J. J.

REF: CS/CT122029.234/Ty 3

ASSIGNMENT

From: _____ Date: _____

Estimated cost: _____

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SMR 3413Z

Policy No. DMPCSNW00263922101

Claims No. SNM22D206691/C02

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: 942K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKG3090C Yr Regn: 2014 June

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Audi A4 c.c. 1798

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 152981 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WPH ZZZ8K7EA-122201

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/55R16

R: u r

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Fallex

Front R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 18/9/2022

Survey held at Prospit Auto.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
21/3/23	Marcus confirmed LS \$11,500 (Red 13,379.80, 53%)

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to?
2) 21/3/23-typist

Rep. Format: Merimen
Lump Sum / T.B.R. (%): \$11,500

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee:	_____
Transportation:	_____
S + RS. SI.	_____
Photos	_____
Others	_____
TOTAL	_____

PROMPT AUTO SOLUTIONS PTE LTD
 promptautosolutions@gmail.com

[Faint, illegible text]

Email: *[illegible]*

Tel: *[illegible]*

VEHICLE NUM:

SKG 3090 C

MAKE & MODEL:

AUDI A4

MILEAGE:

ENGINE NUM:

CHASSIS NUM:

ATTN:

NO.	DESCRIPTION - PARTS	QTY	PRICE	
1	FRONT BONNET	1	\$ 2,890.00	bt ✓
2	FRONT BONNET HINGE LH + RH	2	\$ 286.00	X
3	FRONT BONNET LOCK	1	\$ 254.00	X
4	FRONT BONNET INSULATOR	1	\$ 198.00	X
5	FRONT BONNET INSULATOR CLIP (SET)	1	\$ 80.00	X
6	FRONT BUMPER	1	\$ 1,987.00	de -
7	FRONT BUMPER RETAINER LH + RH	2	\$ 224.00	LHx, RH de -
8	FRONT BUMPER TOWING CAP	1	\$ 89.00	de -
9	FRONT BUMPER FOG LAMP RH	1	\$ 197.00	?
10	FRONT BUMPER FOG LAMP GARNISH RH	1	\$ 182.00	?
11	FRONT BUMPER NOZZLE RH	1	\$ 165.00	?
12	FRONT BUMPER NOZZLE CAP RH	1	\$ 78.00	?
13	FRONT BUMPER SPONGE	1	\$ 145.00	?
14	FRONT BUMPER REINFORCEMENT	1	\$ 847.00	?
15	FRONT BUMPER INNER GARNISH	1	\$ 168.00	?
16	FRONT BUMPER CLIP (SET)	1	\$ 60.00	30mm ✓
17	FRONT GRILLE ASSY	1	\$ 1,606.00	?
18	FRONT GRILLE TOP GARNISH	1	\$ 252.00	X
19	FRONT GRILLE TOP GARNISH CLIP (SET)	1	\$ 50.00	X
20	HEADLAMP LH + RH	2	\$ 7,088.00	LHx, RH car ✓
21	HEADLAMP BRACKET LH + RH	2	\$ 228.00	LHx RH-?
22	FRONT FENDER LH + RH	2	\$ 1,908.00	LHx RH de -
23	FRONT FENDER COWLING RH <i>- photo</i>	1	\$ 256.00	de -
24	FRONT FENDER COWLING CLIP RH	1	\$ 50.00	new - 10
25	FRONT FENDER INNER PANEL RH	1	\$ 231.00	X
26	FRONT SUPPORT PANEL	1	\$ 1,455.00	X
27	FRONT SUPPORT PANEL SIDE GARNISH LH + RH	2	\$ 96.00	LHx, RHx

