

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422 / 6745 4422 Fax : 6747- 6720 REG NO 200501102H

Auto & General Insurance (Singapore) Pte. Ltd
trading as Budget Direct Insurance
190 Clemenceau Avenue, #03-01
Singapore Shopping Centre
Singapore 239924
Tel: 6221 2199

VERON

Quotation

DATE : 20.09.2022
VEH NO : SMG3019L
MODEL : Hyundai Accent
D O A : 18.09.2022
YR REF : SJR596J

Attn : Motor Claim Dept (Pls arrange vehicle surveyor & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SMG3019L (HYUNDAI ACCENT)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Front Bumper <i>Debond</i>	1	474.40 ✓
2	Front Bumper Side Holder - LH & RH <i>LH Debd</i>	2	70.20 35.10 ✓
3	Front Bumper Sponge <i>crushd</i>	1	110.70 ✓
4	Front Bumper Reinforcement <i>Dented</i>	1	289.40 ✓
5	Front Bumper Lower Beam <i>new</i>	1	215.40 x ✓
6	Front Bumper Fog Lamp - LH <i>crushd</i>	1	236.90 ✓
7	Front Bumper Lower Grille <i>new</i>	1	158.40 x ✓
8	Front Grille <i>crushd</i>	1	235.80 ✓
9	Front Grille Logo <i>new</i>	1	39.90 ✓
10	Headlamp - LH <i>crushd</i>	1	825.90 ✓
11	Bonnet <i>Dented</i>	1	1,282.20 ✓
12	Bonnet Lock <i>new</i>	1	5410.90 105.80 x ✓
13	Front Fender - LH <i>Buckled</i>	1	483.90 ✓
14	Front Fender Bracket - LH <i>Best</i>	1	4328.72 45.10 ✓
15	Front Fender Inner Shield - LH <i>Debond</i>	1	156.70 ✓
16	Air Resonator Tank <i>crushd</i>	1	321.40 ✓
17	Fuse Box <i>crushd</i>	1	684.10 ✓
18	Fuse Box Top Cover <i>crushd</i>	1	189.40 ✓

\$ 5,925.60
Less 20% (1,185.12)
\$ 4,740.48

S/NET ITEMS

1	Front Number Plate <i>new</i>	1	30.00 x ✓
2	Front Number Plate Holder <i>new</i>	1	30.00 x ✓
3	Front Bumper Clips <i>new</i>	1 set	30.00 ✓
4	Front Grille Clips <i>new</i>	1 set	20.00 ✓
5	Front Fender Inner Shield Clips - LH <i>new</i>	1 set	30.00 ✓

RE : ESTIMATE FOR ACCIDENT REPAIR SMG3019L (HYUNDAI ACCENT)

6	Front Rim Cover - LH	1	180.00	+
7	Front Rim - LH	1	200.00	+

Total Parts 80 \$ 5,260.48

LABOUR CHARGE

1	To knocking & pull out front portion & renew above parts	\$	1,000.00 800
2	To putty & spray up paint works	\$	1,000.00 700
3	To check wiring system	\$	50.00 30
4	To remove fuse box and to re-wire	\$	300.00 200
5	To perform wheel alignment	\$	150.00 X
Total Labour		\$	2,500.00

Grand Total \$ 7,760.48

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 6138.72

L/S: 4.9K.

07 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: