

ASS. REC. BY: Marcus

REF:

CS / C9122009241/Uny3

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Rear

R/Bal.

L/Bal.

D.O.I.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1) 29/9/22

Date/Time, File Return to?

2)

☐

: Preli. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS SI

) Photos

) Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$


☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$) 6600

)



28/9/22 4/5 \$6600 informed AH Chuen  
(Red, 10919.82, 62%)

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Business
Owner ID:	484A
<b>Vehicle Details</b>	
Vehicle No.:	GBH3087P
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Sep 2022
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 5MT
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	1KD2797479
Chassis No.:	JTFAT35Y30K210356
Maximum Power Output:	-
Open Market Value:	\$27,084.00
Original Registration Date:	18 Apr 2018
First Registration Date:	18 Apr 2018
Transfer Count:	0
Actual ARF Paid:	\$1,355.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	17 Apr 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$29,185.00
COE Rebate Amount:	\$16,268.00
<b>Total Rebate Amount:</b>	<b>\$16,268.00</b>

The information contained herein is correct as at 21 Sep 2022

OK



New Cars

Used Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

This is  
DBS digibankingDBS Business  
Multi-Currency AccountWith easy payments to  
suppliers, I can focus on  
expanding my business.DBS  
SME BANKING

## Post an Advertisement

Sell it yourself! Advertise it at just

**\$68 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

## Honda Civic 1.6L

Lady Owner, Fully Serviced By  
Kah Motor, 5 Years Warranty,  
New Continental Tyres  
Direct Owner StarAdVALUE FOR MONEY  
VALUE FOR TIME  
A PEACE OF MIND

HOTLINE: 6741 9997

view our cars

9 vehicles



Toyota Dyna

Any Category

Sort by Date Posted 20 results/page

Advanced Search



Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	<b>Toyota Dyna</b>	Any	Any	<b>2018</b>	Any	Any	Any	<b>Available</b>
	<b>Toyota Dyna 150 3.0A</b>	<b>\$75,800</b>	\$12,250 /yr	27-Nov-2018	2,982 cc	-	Truck	<b>Available</b>
	<b>Fuel Type:</b> Diesel							
	Auto diesel unit! Powerful and easy to drive! Comes with canopy and checkered plate! Sweet 3 digit number carplate! Tip-top condition,...							<b>PREMIUM AD</b>
	ABS Bus Pte Ltd							
	Posted: 20-Sep-2022							
	<b>Toyota Dyna 150 3.0M</b>	<b>\$71,500</b>	\$12,290 /yr	16-Jul-2018	2,982 cc	-	Truck	<b>Available</b>
	<b>Fuel Type:</b> Diesel							
	Please call in advance before viewing. Thanks!							
	Posted: 20-Sep-2022							
	<b>Toyota Dyna 150 3.0M</b>	<b>\$73,800</b>	\$11,990 /yr	15-Nov-2018	2,982 cc	-	Truck	<b>Available</b>
	<b>Fuel Type:</b> Diesel							
	Most Reliable & Valuable 10FT Truck In The Market. 1 Owner Only. Excellent Condition! No Repair Needed. No Adblue Needed. Grab An...							<b>PREMIUM AD</b>
	SG Motor Link Pte Ltd							
	Posted: 19-Sep-2022							
	<b>Toyota Dyna 150 3.0M</b>	<b>\$72,800</b>	\$11,790 /yr	22-Nov-2018	2,982 cc	-	Truck	<b>Available</b>
	<b>Fuel Type:</b> Diesel							
	Excellent paintwork, interior looks new, clean seat cushion, comes with checker plate and canopy, bank/inhouse loan available, high trad...							<b>PREMIUM AD</b>
	ABS Bus Pte Ltd							
	Posted: 15-Sep-2022							
	<b>Borneo Motors announces digital solutions</b>							
	Borneo Motors announces the roll-out of digital enchantments to provide a suite of end-to-end customer solutions to redesign the after sales experience.							
	<a href="#">Read this article</a>							
	<b>Toyota Dyna 150 3.0M</b>	<b>\$65,800</b>	\$12,370 /yr	15-Jan-2018	2,982 cc	72,200 km	Truck	<b>Available</b>
	<b>Fuel Type:</b> Diesel							
	The most durable & valuable 10ft truck on the market right now! Buying secondhand trucks to ease up on financial commitments. Also A...							<b>PREMIUM AD</b>
	Car (S) Pte Ltd							
	Posted: 13-Sep-2022							
	<b>Toyota Dyna 150 3.0M</b>	<b>\$68,000</b>	\$12,420 /yr	13-Mar-2018	2,982 cc	73,933 km	Truck	<b>Available</b>
	<b>Fuel Type:</b> Diesel							
	Silver freezer truck.							<b>DIRECT OWNER</b>
	Posted: 08-Sep-2022							

Compare

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged parts, during re-survey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

利民达摩多



## Jementah Motor Works

Blk 14 Defu Lane 10 #01-406

Singapore 539195

H/P : 9299 6636 Fax : 6285 7054

Date : 16-Sep-22

not Authorised  
mercus. hr  
21/09/22  
2/54 6600/  
Telephone Attorney  
6 days

### Estimated repair cost of GBH 3087 P TOYOTA DYNA

Qty	Description	Amt S(\$)
<u>List Items</u>		
1	Wiper panel <i>DP/wiper</i>	\$ 262.50 ✓
1	Wiper motor linkage <i>11</i>	\$ 198.00 X
2	Front headlamps <i>one</i>	\$ 2,161.00 ✓
2	Front side lamps <i>NS</i>	\$ 305.80 X
1	Front panel <i>Body</i>	\$ 1,066.50 ✓
1	Front panel "DYNA" emblem <i>new</i>	\$ 58.50 ✓
2	Front corner panels <i>2</i>	\$ 553.00 X
1	Front grille assy <i>one</i>	\$ 648.69 ✓
1	Front grille clip set <i>new</i>	\$ 68.50 ✓
1	Front grille logo <i>new</i>	\$ 75.00 ✓
1	Front bumper <i>Dis</i>	\$ 682.80 ✓
2	Front bumper brackets <i>Brp</i>	\$ 316.00 ✓
1	Air con blower unit <i>one</i>	\$ 917.40 ✓
1	Air con cooling coil <i>11</i>	\$ 629.00 X
2	Rear chassis members <i>2</i>	\$ 1,970.40 X
		\$ 9,913.09
	Less 25%	\$ 2,478.27
		\$ 7,434.82
<u>Special Nett Items</u>		
1	Front number plate <i>Brp</i>	\$ 45.00 20
1	Rear bumper assy <i>Brp</i>	\$ 1,200.00 600
1	Rear number plate <i>Brp</i>	\$ 50.00 20
1	Rear reverse sensor (1 set) <i>should</i>	\$ 350.00 200
1	Rear stopper rubber set <i>see</i>	\$ 480.00 X
1	Rear freezer door stainless steel frame <i>11</i>	\$ 3,500.00 X
		\$ 5,625.00

S/N

### LABOUR CHARGES

1	To check wiring and reset headlamps focusing.	\$ 80.00
2	To remove, replaced damaged lamps and check up rear wiring.	\$ 80.00 330
3	To remove and refit rear reverse sensor.	\$ 120.00 50
4	To remove, replace air-con condenser, refill gas & conduct leakage test.	\$ 180.00 100
5	To apply undercoating.	\$ 200.00 50
6	Panel beating.	\$ 2,000.00 1500
7	To re-spray painting on the affected areas.	\$ 1,800.00 1000
		\$ 4,460.00

Grand Total :

\$ 17,519.82

P-625689  
252  
4692.66  
840  
2730