

YSK AUTO WORKSHOP

1 Kaki Bukit Avenue 6, Blk D #01-71

Registration No. / Unique Entity Number: 53311047E

Estimate for SLV8832E(BMW 520D)

- 1 *LH TENSION STRUT WITH HYDR MOUNT *new*
- 1 *WISHBONE TOP *new*
- 1 *LH WISHBONE BOTTOM RUBBER MOUNT *new*
- 1 *WHEEL HUB WITH BEARING FRT *new*
- 1 *FRT LH SPRING STRUT *new*
- 1 *FRONT SWING SUPPORT *new*
- 1 *STABILIZER FRT WITH RUBBER MOUNTING *new*
- 1 *LH TIE ROD *new*
- 1 *ALLOY RIM 91/2JX19 STY SPOKE 272 *new*
- 1 *FRT LH FENDER *Disturbed.*
- 1 *FRT LH FENDER SHIELD *torn*
- 1 *FRT BUMPER CARRIER *new*
- 1 *IMPACT ABSORBER TOP *new*
- 1 *FRT BUMPER (PDC) *Disturbed.*
- 1 *COVERING PRIMED LH *new*
- 1 *COVERING PRIMED RH *new*
- 1 *BMW EMBLEM *new*
- 1 *AHL XENON HEADLIGHT LH LED MODULE *new*
- 1 *AHL XENON HEADLIGHT LH *covered*
- 6 *DECOUPLING RING PDC TORQUE CONVERTE *new*
- 6 *BUMPER PDC SENSOR (A90 SOPHISTOGRAU *2 pieces damaged*
- 1 *FRT BUMPER LH SPACER *new*
- 1 *FRT BUMPER RH SPACER *new*

Less 5%

- *FRONT BUMPER CLIPS *new*
- *FRONT LH SPLASH SHIELD CLIPS *new*
- *FRONT LH TYRE *new*

- REPLACE AND REMOVE ATTACHMENT ETC INCLUDE KNOCK ON ACCIDENT DENT
- SPRAY PAINTING DAMAGED PORTION
- TO TOW ACCIDENT VEHICLE TO WORKSHOP
- TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT
- TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING LEFT FRONT

To perform diagnostic test

*T? Somp.
Hui Key.
WBAJc32080G580853.*

\$492.90	X
\$542.20	X
\$591.50	X
\$1,006.00	<i>577.</i>
\$600.85	<i>298</i>
\$221.20	✓
\$469.25	+
\$352.90	X
\$1,508.60	<i>850(IN).</i>
\$884.85	✓
\$325.20	✓
\$698.50	X
\$45.60	+
\$1,403.10	✓
\$86.45	+
\$86.45	+
\$69.50	✓
\$285.10	X
\$4,960.90	✓
\$120.20	✓
\$1,475.20	<i>490</i>
\$88.65	✓
\$88.65	X
\$16,403.75	
\$820.19	
\$15,583.56	
\$80.00	<i>30</i>
\$80.00	<i>30.</i>
\$800.00	X
\$960.00	
\$1,000.00	<i>500</i>
\$1,000.00	<i>500</i>
\$150.00	<i>80.</i>
\$150.00	<i>80</i>
\$50.00	✓
200.	<i>120.</i>

60

TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR
PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS

~~\$120.00~~

50

TO CARRY OUT BODY CAVITY PRESERVATION

~~\$120.00~~

50

TO REMOVE AND INSTALL FRONT SUSPENSION FOR INSPECTION AND
REPLACE DAMAGED PARTS

~~\$250.00~~

150

1580

\$2,840.00

Total

\$19,383.56

Adrian Lj
h/c 20/09/22
05hys.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 11901.67

h/s: 9.51c

9.51c