

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

A			Affiliated to Federation Internationale Des Experts En Automobile				
	XA INSURANCE F	PTE LTD	Ref:	CS/ASM22009248/Uwy3m4			
	SHENTON WAY FOWERSINGAPOR	_	Date:	06/12/2022			
ТА	TTN: TEO KITTY		Code:	ASM			
1.	Policy Particulars :- THIRD PARTY CLAIM						
In	sured Veh.	SHC 410P	Veh. Inspected	SKV 5593B			
Po	olicy No.	VFX/P2419140	Coverage (\$)	0.00			
CI	laim No.	S2M04B8P	Excess (\$)	0.00			
As	ssign From	TEO KITTY	Assign Date	20/09/2022			
2. Vehicle Particulars & Condition							
M	ake & Model	HONDA JAZZ (A)	c.c	1498			
Er	ngine No.	HIDDEN	Year of Reg.	2015			
CI	hassis No.	JHMGK5850GX200345	Colour	BLUE			
0	dometer	115869 KM	Steering	IN ORDER			
Br	rakes	IN ORDER	Modification	SPORTS RIM			
G	eneral	GOOD					
3. Conditions of Tyres							
		Size	Make	Balance			
R/	/H Front Tyre	185/55 R16	MICHELIN	7 mm			
L/	/H Front Tyre	185/55 R16	MICHELIN	7 mm			
R/	/H Rear Tyre	185/55 R16	MICHELIN	7 mm			
L/	/H Rear Tyre	185/55 R16	MICHELIN	7 mm			
4.	Description of Damages						
T⊦	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.						
DA	DAMAGES SEE DETAILS.						
5.	General Information						
Ad	ccident Date	18/09/2022	Inspection Date	28/09/2022			
Sı	urvey held at	PRECISE AUTO SERVICE	•				
		NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883					
5a.	n. Remarks						
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.						
5b.	Estimate Days of Repair						
3D.							