

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. CB 8040K

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILGATE	BENT	2,150.00	2,150.00
1	REAR WINDSCREEN	CRACKED	680.00	680.00
6	REAR FENDER LH	BUCKLED	3,940.00	3,940.00
1	REAR FENDER GLASS LH	* CHECK	950.00	-
1	REAR BUMPER	DEFORMED	1,355.00	1,355.00
1	REAR TAILLAMP LOWER BRACKET LH	SCRATCHED	355.00	355.00
1	REAR TAILLAMP LH	BROKEN	415.00	415.00
1	BODY STICKER	NECESSARY	80.00	80.00
	LESS 10% DISCOUNT		-	-897.50
			9,925.00	8,077.50
	SPECIAL NETT ITEMS			
1	SUNDRIES (SN)	NECESSARY	200.00	50.00
			200.00	50.00
	<u>LABOUR</u>			
	LABOUR TO REMOVE AND CHECK REAR BUMPER AND TAILGATE WIRE HARNESS.		500.00	100.00
	LABOUR TO REMOVE, AND REINSTALL REAR WINDSCREEN AND REAR FENDER GLASS LH.		650.00	300.00
	LABOUR TO REMOVE, AND REINSTALL ELECTRICAL, AUDIO EQUIPMENT AND SEAT PASSENGER, CHECK ACCORDING TO DAMAGE.		650.00	250.00
	LABOUR TO REMOVE, REPAIR AND REINSTALL REAR BUMPER, REAR FENDER LH AND TAILGATE.		5,200.00	2,250.00
	LABOUR TO RESPRAY REAR BUMPER, REAR FENDER LH, REAR BUMPER AND REAR TAILLAMP LOWER BRACKET LH.		3,200.00	2,000.00
	LABOUR TO CARRY OUT DIAGNOSTIC CHECK.		250.00	80.00
			10,450.00	4,980.00
	GRAND TOTAL		20,575.00	13,107.50



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS		13,107.50
(REPAIR COST NOT CONCLUDE)		·
(EXCLUDE CHECK ITEMS S\$855.00 NETT)		

Report Ref No. CS/GAI22009255/Rvy3e2

MKB

MOHAMMED RASUL BIN MOHD YUNUS

**Automotive Assessor** 

X.S.

**ADRIAN LING WAI PING** 

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

**Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replyin

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.