

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : GBK 9634J

Date : 20.09.2022

Vehicle Model : TOYOTA HIACE

Chassis : JTFHT02P500251169

Accident Date : 19.08.2022

TP Ins. **LONPAC**

Original Reg Date : 15.01.2021

ESTIMATE

1	1 pc	Sliding Door RH		Rp 1,718.80
2	1 pc	Sliding Door Railing RH - photo		cut 292.00
3	1 pc	Rear Side Panel RH		bt 1,986.50

1517.80

3,997.30 1809.80

Less 25% 999.33 1357.35

2,997.98

Labour charge

Panel Beating	700	1,000.00
Spray painting	600	1,000.00
Check Wiring	nnx	40.00
Anti rust	40	90.00
Remove and install carpet and interior	100	250.00
Remove and install sliding door part	nnx	90.00

1440

5,467.98

Less 20% 1,093.60

Lump sum **4,374.38**

Tan M 97495749
wp 20/9/22C /pm

cls using after repair
4 days

Tan M C Chantoon

1357.35

1440

2797.35

4582200

04 days

*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications, is allowed
- Supplementary items must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date: