


PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0811/2022/EQ
DATE : 19-Sep-22
WIP : 42279

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 20/09/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR TAN PENG CHEOK
ADDRESS : 7 SPRINGSIDE PLACE
SINGAPORE 786410

TELEPHONE : HP +65 96660442
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100488912-05
VEHICLE NO : SDR 318 S
MODEL CODE : AUDI A3 SEDAN 1.4 TFSI
MODEL YEAR : 10/11/2016
ENGINE NO : CZC 576661
CHASSIS NO : WAUZZZ8V3G1113363
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 16-Sep-22
PLACE OF ACCIDENT : SIMS AVENUE TOWARDS PAYA LEBAR ROAD NEAR LOR 35
GEYLANG



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDR 318 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. RENEW ACCORDING TO DAMAGES.	S/N \$ 360.00 /	
2	TO CARRY OUT FIRST MEASUREMENT ON CAR-O-LINER.	S/N \$ 800.00 ✓ 7	
3	TO REMOVE AND REINSTALL CENTER CONSOLE. RENEW SEAT BELTS AND CONTROL UNIT, PILLAR TRIMS, ROOF LINING, RHS CURTAIN AIRBAG, RHS DRIVER SIDE AIRBAG AND LEATHER COVER.	S/N \$ 2,800.00 /	
4	TO RENEW REAR WINDSCREEN AND RHS 1/4 GLASS TO FACILITATE THE RENEWAL OF RHS REAR FENDER.	S/N \$ 600.00 /	
5	TO RENEW SOLAR FILM FOR AFFECTED GLASSES.	TBC X 7	
TOTAL LABOUR CHARGES		: \$ 4,560.00	



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDR 318 S

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN AND 1/4 GLASS.	S/N \$	200.00	150 ✓
7	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. (photo)	S/N \$	1,400.00	✓
8	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, LUGGAGE COMPARTMENT TRIMS. (photo)	S/N \$	1,400.00	✓
9	TO REMOVE AND RENEW RHS REAR SUSP ASSY WITH SUBFRAME.	S/N \$	2,400.00	X ✓
10	TO SET UP AND PLACE VEHICLE ON CAR-O-LINER.	S/N \$	2,400.00	✓
TOTAL LABOUR CHARGES		:	\$ 7,800.00	



55 UBI ROAD 1, SINGAPORE 408699


TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDR 318 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
11	TO DISMANTLE REAR BUMPER. RENEW RHS REAR DOOR, CUT OUT AND WELD RHS REAR FENDER, INNER C-PILLAR REINFORCEMENT, RHS OUTER WHEEL HOUSE AND SILL PANEL. RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	8,400.00	3500 ✓
12	TO REMOVE AND REINSTALL RHS FRONT DOOR WING MIRROR ASSY.	280.00	✓
13	TO RESPRAY RHS FRONT AND REAR DOORS, RHS REAR FENDER, INNER PANELS, RHS SILL PANEL, ROOF CHANNEL, DRAIN CHANNEL, DOOR ENTRANCE AND REAR END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS.	6,250.00	3075 ✓
14	TO RENEW RHS REAR RIM AND CARRY OUT PRE/POST WHEEL ALIGNMENT.	520.00	180 ✓
15	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	384.00	✓
TOTAL LABOUR CHARGES		28,194.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDR 318 S

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	REAR DOOR - RH / <i>OD</i>	1	\$	3,265.00 ✓	<i>2612</i>
2	REAR OUTER DOOR SEAL - RH / <i>MC</i>	1	\$	179.00 ✓	<i>142.80</i>
3	BONDING AGENT / <i>MC</i>	1	\$	51.00 ✓	<i>40.56</i>
4	CLEANING SOLUTION / <i>MC</i>	1	\$	74.00 ✓	<i>58.96</i>
5	APPLICATOR / <i>MC</i>	1	\$	9.00	
6	REAR DOOR CATCH - RH ? X nn	1	\$	105.00	
7	REAR DOOR INNER SEAL - RH / <i>CR4</i>	1	\$	213.00 ✓	<i>170.40</i>
8	REAR DOOR ATTACHMENT PARTS ? X nn	1	\$	134.00	
9	REAR DOOR HANDLE - RH X R	1	\$	398.00	
10	REAR DOOR SLIDE VALVE - RH ? X nn	1	\$	25.00	
11	REAR DOOR HOUSING - RH ? X nn	1	\$	58.00	
12	REAR DOOR MOUNTING BAR - RH ? X nn	1	\$	182.00	
13	REAR DOOR BOWDEN CABLE ? X nn	1	\$	58.00	
14	REAR DOOR BOWDEN CABLE HOLDER ? X nn	1	\$	4.00	
15	REAR DOOR LOCK - RH ? X nn	1	\$	630.00	
16	REAR DOOR STRIKER ? X nn	1	\$	69.00	
17	REAR DOOR BOWDEN CABLE ? X nn	1	\$	43.00	
18	REAR WINDOW GUIDE - RH ? X nn	1	\$	467.00	
19	REAR WINDOW GUIDE TRIM STRIP - RH ? X nn	1	\$	250.00	
20	REAR WINDOW SLOT SEAL TRIM STRIP - RH ? X nn	1	\$	331.00	
SUB TOTAL SPARE PARTS			:	\$ 6,545.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDR 318 5

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR DOOR PANEL INNER COVER - RH ? X nn	1	\$ 28.00	
22	REAR DOOR PANEL - RH <i>WAB</i> ? X nn	1	\$ 1,831.00	
23	REAR DOOR WINDOW FRAME TRIM - RH ? X nn	1	\$ 134.00	
24	REAR WINDOW REGULATOR - RH ? BT	1	\$ 286.00	✓ 228.40
25	REAR WINDOW GUIDE RAIL - RH ? X nn	1	\$ 58.00	
26	REAR DOOR CONTROL UNIT ? X nn	1	\$ 443.00	
27	REAR WINDOW REGULATOR MOTOR - RH ? X nn	1	\$ 300.00	
28	REAR SIDE PANEL - RH / <i>OP</i>	1	\$ 3,662.00	✓ 3929.60
29	REAR WHEEL HOUSING LINER / <i>CK4</i>	1	\$ 260.00	✓ 208
30	REAR WHEEL HOUSING LINER ATTACHMENT PARTS / <i>NE</i>	1	\$ 93.00	64.30 ✓ 51.44
31	REAR WINDOW / <i>NE</i>	1	\$ 905.00	✓ 724
32	REAR WINDOW PRIMER / <i>NE</i>	1	\$ 22.00	✓ 17.36
33	REAR SIDE WINDOW - RH - <i>NE</i>	1	\$ 635.00	✓ 508
34	REAR SIDE WINDOW PRIMER - <i>NE</i>	1	\$ 22.00	✓ 17.36
35	REAR WHEEL HOUSING INNER - RH ? X nn	1	\$ 673.00	
36	C-PILLAR PLATE - LOWER ? X nn	1	\$ 15.00	
37	C-PILLAR LOWER REINFORCEMENT - RH ? X nn	1	\$ 211.00	
38	C-PILLAR THREADED PLATE - RH ? X nn	1	\$ 36.00	
39	C-PILLAR PLATE - LOWER ? X nn	1	\$ 15.00	
40	C-PILLAR SIDE MEMBER - RH ? X nn	1	\$ 434.00	
SUB TOTAL SPARE PARTS		:	\$ 10,063.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDR 318 S

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	REAR WHEEL HOUSING TRIM - RH / CRU	1 S	149.00 ✓	119.00
42	ROOF LINER / CRU	1 S	2,113.00 ✓	1690.40
43	HEAD AIRBAG UNIT / BR	1 S	2,069.00 ✓	1655.00
44	REAR BACKREST COVER - RH (F4 RH) / BR	1 S	2,449.00 ✓	159.00
45	SIDE AIRBAG UNIT / BR	1 S	1,688.00 ✓	1350.40
46	THREE-POINT AUTOMATIC SEAT BELT - LH / RH / just	(2) S	2,454.00 ✓	1963.00
47	SEAT BELT HEIGHT ADJUSTER - LH / RH ? NEC	2 S	430.00 ✓	344
48	AIRBAG CONTROL UNIT / M	1 S	1,923.00 ✓	1538.40
49	AIRBAG CRASH SENSOR ? X nn	1 S	449.00	
50	FRONT GRAB HANDLE - LH / RH ? X nn	2 S	326.00	
51	REAR GRAB HANDLE - LH / RH ? X nn	2 S	326.00	
52	REAR ALUMINIUM RIM - RH / M	1 S	1,303.00 ✓	1042.40
53	REAR ALUMINIUM RIM RUBBER VALVE - RH / M	1 S	8.00 2.96 ✓	296
54	REAR CROSS MEMBER ? X nn	1 S	1,844.00	
55	REAR CROSS MEMBER - FRONT ? X nn	2 S	200.00	
56	REAR CROSS MEMBER - REAR ? X nn	2 S	200.00	
57	REAR WHEEL BEARING HOUSING - RH ? X nn	1 S	666.00	
58	REAR WHEEL BEARING HOUSING BONDED RUBBER BUSH ? X nn	1 S	31.00	
59	REAR WHEEL BEARING ASSEMBLY PARTS ? X nn	1 S	486.00	
60	REAR TRACK ROD - RH ? X nn	1 S	119.00	
SUB TOTAL SPARE PARTS		:	\$ 19,233.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDR 318 S

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
61	REAR LOWER ARM - RH ? X nn	1	\$ 347.00	
62	REAR WISHBONE - RH ? X nn	1	\$ 300.00	
63	BONDED RUBBER BUSH ? X nn	1	\$ 31.00	
64	REAR UPPER WISHBONE - LH / RH ? X nn	1	\$ 300.00	
65	REAR GAS SHOCK ABSORBER - RH ? X nn	1	\$ 276.00	
66	ACRYLIC SEALER ? - KC	S/N	\$ 180.00 ✓	180
67	CAVITY WAX - KC	S/N	\$ 140.00 ✓	140
68	STONE CHIPS - KC	S/N	\$ 180.00 ✓	180
69	METAL FILLER POWDER - KC	S/N	\$ 280.00 ✓	280
70	REAR WINDSCREEN SEALANT - KC	S/N	\$ 200.00 ✓	200
71	1/4 GLASS SEALANT - KC	S/N	\$ 100.00 ✓	100
72	SUNDRIES ? NEC		\$ 900.00	127.76 ✓
TOTAL SPARE PARTS		:	\$ 39,075.00	
TOTAL LABOUR CHARGES		:	\$ 28,194.00	
GRAND TOTAL		:	\$ 67,269.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

:
:
:
:
:
:

Steve CLKK)
20/9/12, 4.45 PM

OP L4 AL
EXCESS - ?
P/P
L4 BL Y
23 20 1183 dy

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0811/2022/EQ
15-Oct-22
CHANG
1 of 1
SDR 318 S
AUDI A3 SEDAN 1.4 TFSI

Quantity	Description	Unit Price	Amount
Parts			
1	A-PILLAR TRIM - RH / DR	\$ 182.00 ✓	145.60
2	FUEL FLAP THROTTLE CONTROL ELEMENT 1 / ne	\$ 79.00 ✓	68.96
GRAND TOTAL		\$ 261.00	

Steve (CLKK)
17/10/22

For Premium Automobiles Pte Ltd



Authorised Signature



PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-2

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0811/2022/EQ

3-Nov-22

CHANG

1 of 1

SDR 318 S

AUDI A3 SEDAN 1.4 TFSI

Quantity	Description	Unit Price	Amount
Parts			
1	FUEL INSERT ✓ BR 1	\$ 188.00	✓ 148.40
GRAND TOTAL		\$ 188.00	

For Premium Automobiles Pte Ltd

Steve CLKK1

3/11/22



Authorised Signature

Add 3 days (Caroline & setup)



PREMIUM AUTOMOBILES



55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 . Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate-2

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0811/2022/EQ 15-Mar-23 GLORY 1 of 1 SDR 318 S AUDI A3 SEDAN 1.4 TFSI	
Quantity	Description		Unit Price	Amount
LABOURS				
1	rear TO REMOVE AND RENEW R H S FRONT SEAT BACKREST.	S/N	\$ 780.00	\$ 780.00
GRAND TOTAL			\$ 780.00	\$ 780.00

For Premium Automobiles Pte Ltd

Authorised Signature