LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.

79 Robinson Road #09-01 Singapore 068897 From: LKK Auto Consultants Pte Ltd

Est. Duration of Repair

: 4

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Sharon Lim Date: 22 Sep 2022

Preliminary Advice

 Vehicle No
 : SGC730C
 Accident Date
 : 18/09/2022

 Make
 : BMW X3
 Policy No.
 : 202222006903SL

Assignment Date : 21/09/2022 Excess : S\$700.00

Date of Inspection : 22/9/2022 Inspection At : OPTIMA WERKZ PTE LTD

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,578.00
Revised Amount	:S\$	5,685.00
Check Items (Estimated)	:S\$	150.00
Total	:S\$	5,835.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 64,000.00 COE / PARF Rebate :S\$ 35,996.00

Salvage Value :S\$

Margin for Repair :S\$ 28,004.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
	Kindly let us have your authorisation.

- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Lump Sum Repair

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .