




JACK CARS

DRIVE WITH ASSURANCE

ESTIMATE

DATE OF ACCIDENT : 20/09/2022
VEHICLE : SMN3664L
MAKE & MODEL : MERC CLA 180
INSURANCE : AUTO & GENERAL
SURVEYOR : LKK

PARTS		AMOUNT
1.	REAR BUMPER <i>X Repair.</i>	\$ 2500
2.	REAR BOOT <i>X Repair</i>	\$ 3200
SPECIAL NETT		
1.	WRAPPING <i>/ cut .</i> 600.00	\$ 1800 <i>450</i>
2.	CLIPS , SCREWS & RIVETS <i>X NN</i>	\$ 100
LABOUR		
1.	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	\$ 1800 <i>450</i>
2.	TO PANEL BEAT & TO REMOVE DAMAGED & NECESSARY PARTS & ATTACHEMENTS; KNOCK, JACK, WELD, RESHAPE AND ALIGN ALL AFFECTED PORTIONS.	\$ 1500 <i>400</i>
3.	TO CHECK LIGHTING SYSTEM ,WIRING & REWIRE	\$ 150 <i>X</i>
4.	TO REMOVE AND REINSTALL TAILGATE COMPONENTS	\$ 220 <i>X</i>



JACK CARS

DRIVE WITH ASSURANCE

5.	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY	N/A	\$ 280	X
6.	TO REMOVE & REINSTALL SENSORS		\$ 200	40
		PARTS - 10%:	\$ 5,130	
		SPECIAL NETT :	\$ 1,900	
		LABOUR :	\$ 4,150	
		TOTAL :	\$ 11,180	
		7% GST :	\$ 782.60	
		GRAND TOTAL :	\$ 11,962.60	

3 Days.

before & after paint photos.

Quo Giap

4/10/22

LKK Auto Consultants hence notify the Repairer of the following:	
• To resurvey before/after spray painting	
• To display dan	resurvey
• Parts price	on
• Third party	judico* basis
• No illegal	
• Supp	and
is sub	the Company
Acknowled	
Signature	
Date:	