

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933 Tel: 68441985 Fax: 68445185

TAX INVOICE

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way
#07-16, Singapore 079120

GST Ref. No: M2-0111811-5

Vehicle No: SGR 1008U
Chasis No : WDD2130422A501964
Engine No: 27492031577191

Invoice No: G23SINVP000498

Invoice Date: 3/3/2023

DESCRIPTION	AMOUNT SGD
-------------	---------------

Parts

No.	Qty.	Description	Price (SGD)
1	1	RR BUMPER CENTRE	1650.00

Total: 1650.00
Less 10%: 165.00
Parts Total : 1485.00

Labour

No.	Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair	250.00
2	Carry out spray painting on accident affected area. (Rear bumper)	250.00
3	Remove and replace reverse sensor (Labour)	50.00

Labour Total : 550.00

Sub Total : 2035.00
GST (8%) 162.80
Grand Total: 2197.80

Yours Faithfully,



Ronnie Tan
Service Advisor
Tel: 68441985 Fax: 68445185

E & O E

- ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO "1ST AUTOWORKS PTE LTD".
- PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE.