

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 21.09.2022

TO : AXA MOTOR CLAIMS DEPTS
VEHICLE NO : SLV8818Y
MODEL : TOYOTA VOXY
DATE OF ACCIDENT : 21.09.2022
TIME OF ACCIDENT : 09:15 HRS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT DOOR LH	1	\$ 1,675.00	\$ 1,675.00
2	FRONT DOOR OUTER STRIP LH	1	\$ 175.00	\$ 175.00
3	FRONT DOOR WEATHER STRIP LH	1	\$ 279.30	\$ 279.30
4	FRONT DOOR STOPPER LH	2	\$ 19.80	\$ 39.60
5	FRONT DOOR HINGE (UPPER) LH	1	\$ 80.00	\$ 80.00
6	FRONT DOOR HINGE (LOWER) LH	1	\$ 80.00	\$ 80.00
7	FRONT DOOR INNER LOCK LH	1	\$ 581.70	\$ 581.70
8	FRONT DOOR INNER TRIM LH	1	\$ 1,864.30	\$ 1,864.30
9	FRONT DOOR POWER WINDOW MOTOR LH	1	\$ 647.20	\$ 647.20
10	FRONT DOOR REGULATOR LH	1	\$ 387.60	\$ 387.60
11	FRONT DOOR SPEAKER LH	1	\$ 357.90	\$ 357.90
12	FRONT DOOR BLACK STICKER LH	1	\$ 174.30	\$ 174.30
13	FRONT DOOR FRAME WEATHER STRIP LH	1	\$ 289.80	\$ 289.80
14	SIDE SKIRT LH	1	\$ 1,125.30	\$ 1,125.30
15	SLIDING DOOR LH	1	\$ 1,585.00	\$ 1,585.00
16	SLIDING DOOR STRIP SENSOR LH	1	\$ 971.50	\$ 971.50
17	SLIDING DOOR OUTER STRIP LH	1	\$ 1,300.00	\$ 1,300.00
18	SLIDING DOOR POWER WINDOW MOTOR LH	1	\$ 487.10	\$ 487.10
19	SLIDING DOOR AUTO SYSTEM MOTOR	1	\$ 1,993.90	\$ 1,993.90
20	SLIDING DOOR STICKER (BLACK) (SET)	1	\$ 210.00	\$ 210.00
21	SLIDING DOOR FRONT INNER LOCK LH	1	\$ 618.10	\$ 618.10

TO : **AXA** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLV8818Y**
 MODEL : **TOYOTA VOXY**
 DATE OF ACCIDENT : 21.09.2022
 TIME OF ACCIDENT : 09::15 HRS

22	SLIDING DOOR INNER TRIM LH	1	\$ 1,897.40	\$ 1,897.40
23	SLIDING DOOR FRAME WEATHER STRIP LH	1	\$ 577.40	\$ 577.40
24	SLIDING DOOR STEP PANEL LH	1	\$ 633.70	\$ 633.70
25	SLIDING DOOR STEP PANEL GARNISH LH	1	\$ 498.80	\$ 498.80
26	SLINDING DOOR WEATHERSTRIP LH	1	\$ 298.00	\$ 298.00
27	SLIDING DOOR BACK INNER LOCK	1	\$ 524.30	\$ 524.30
28	SLINDING DOOR LOWER ROLLER LH	1	\$ 285.00	\$ 285.00
29	SLINDING DOOR LOCK CATCH LH	1	\$ 78.00	\$ 78.00
30	REAR FENDER LH	1	\$ 850.00	\$ 850.00
31	REAR FENDER ARCH SEAL LH	1	\$ 138.10	\$ 138.10
32	REAR FENDER LOWER GUARD LH	1	\$ 148.10	\$ 148.10
33	REAR FENDER COWLING LH	1	\$ 158.10	\$ 158.10
34	REAR FENDER INNER SHIELD LH	1	\$ 218.10	\$ 218.10
35	REAR FENDER GLASS WITH MOULDING	1	\$ 930.00	\$ 930.00
36	REAR ABS SENSOR LH	1	\$ 398.00	\$ 398.00
37	REAR SHOCK ABSORBER LH	1	\$ 395.00	\$ 395.00
38	REAR WHEEL HUP WITH BEARING LH	1	\$ 995.00	\$ 995.00
39	REAR AXLE	1	\$ 3,150.00	\$ 3,150.00
40	REAR BUMPER	1	\$ 1,450.00	\$ 1,450.00
41	REAR BUMPER SIDE BRACKET	2	\$ 78.00	\$ 156.00
42	REAR BUMPER SIDE RETAINER	2	\$ 78.00	\$ 156.00

TOTAL PRICE \$ 28,857.60
 LESS 25% \$ 7,214.40
SUB TOTAL PRICE \$ 21,643.20

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT DOOR INNER TRIM CLIP	1	\$ 60.00	\$ 60.00
2	SLIDING DOOR INNER TRIM CLIP RH (SET)	1	\$ 60.00	\$ 60.00
3	REAR FENDER SEALANT LH	1	\$ 80.00	\$ 80.00
4	REAR FENDER COWLING CLIP LH (SET)	1	\$ 50.00	\$ 50.00
5	REAR FENDER INNER TRIM CLIP	1	\$ 60.00	\$ 60.00
6	REAR FENDER INNER SHIELD CLIP LH (SET)	1	\$ 30.00	\$ 30.00
7	REAR FENDER GLASS SOLAR FILM	1	\$ 300.00	\$ 300.00
8	REAR FENDER GLASS INNER SEAL	1	\$ 60.00	\$ 60.00
9	REAR FENDER GLASS SEALANT	1	\$ 80.00	\$ 80.00

TO : **AXA** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLV8818Y**
 MODEL : **TOYOTA VOXY**
 DATE OF ACCIDENT : 21.09.2022
 TIME OF ACCIDENT : 09::15 HRS

10	REAR WHEEL TYRE LH	1	\$ 450.00	\$ 450.00
11	REAR WHEEL RIM LH	1	\$ 1,200.00	\$ 1,200.00
12	WHEEL CAP (SET)	1	\$ 120.00	\$ 120.00
13	REAR BUMPER CLIP (SET)	1	\$ 50.00	\$ 50.00
14	STEP PANEL GARNISH CLIP	1	\$ 60.00	\$ 60.00
15	DOOR CHROME MOULDING (SPECIAL TYPE)	1	\$ 800.00	\$ 800.00
16	DOOR VISOR (SET)	1	\$ 300.00	\$ 300.00
17	BRAKE OIL	1	\$ 30.00	\$ 30.00

TOTAL \$ 3,790.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,200.00	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	
3	TUFF COAT	\$ 250.00	
4	WIRING CHECK	\$ 150.00	
5	REMOVE AND REFIX FUEL TANK	\$ 120.00	
6	TRANSFER FRONT DOOR MECHANISM RH	\$ 80.00	
7	REMOVE & REINSTALL FRONT WINDOW GLASS RH	\$ 60.00	
8	REMOVE AND REFIX REAR FENDER QUARTER GLASS RH	\$ 120.00	
9	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 250.00	
10	REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 550.00	
11	TO PRESS REAR WHEEL BEARING	\$ 80.00	
12	FOUR WHEEL ALIGNMENT	\$ 120.00	

TO : **AXA** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLV8818Y**
 MODEL : **TOYOTA VOXY**
 DATE OF ACCIDENT : 21.09.2022
 TIME OF ACCIDENT : 09::15 HRS

13	TRANSFER SLIDING DOOR MECHANISM RH	\$ 80.00	
14	REMOVE, REFIX AND RESET SLIDING DOOR AUTO SYSTEM	\$ 350.00	
15	REMOVE & REINSTALL REAR WINDOW GLASS	\$ 60.00	
16	CONDUCT WATER LEAKAGE TEST	\$ 120.00	
17	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	
18	RESET ABS LIGHT	\$ 350.00	
19	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	

TOTAL \$6,800.00

TOTAL PARTS COST : \$ 25,433.20
 TOTAL LABOUR COST : \$ 6,800.00
 TOTAL REPAIR COST : \$ 32,233.20

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE
 CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED
 ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787