



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705		Ref: CS/SMR22009323/Uny3m4 Date: 18/10/2022 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 4865J	Veh. Inspected	FBR 9211E
Policy No.		Coverage (\$)	0.00
Claim No.	TAX/09/22/2036	Excess (\$)	0.00
Assign From	HUA YEN	Assign Date	21/09/2022
2. Vehicle Particulars & Condition			
Make & Model	YAMAHA XT1200Z	c.c	1199
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	JYADP011000008199	Colour	BLUE
Odometer	160823 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	110-80-19	BRIDGESTONE	7 mm
L/H Front Tyre			mm
R/H Rear Tyre	160-70-17	BRIDGESTONE	7 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	17/09/2022	Inspection Date	22/09/2022
Survey held at	ERZAT LEE MOTOR TRADING PTE LTD 25 KAKI BUKIT ROAD 4, #03-37, SYNERGY @ KB, SINGAPORE 417800		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	