

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: India International Insurance Pte Ltd  
64 Cecil Street  
#04-00 IOB Building  
Singapore 049711

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Bhargavi Purushothaman Dhanya

Date: 23 Sep 2022

## **Preliminary Advice**

Vehicle No	: SNF904U	Accident Date	: 06/09/2022
Make	: TOYOTA NOAH HYBRID	Policy No.	: D18MFL0003414_03
Assignment Date	: 22/09/2022	Excess	: S\$0.00
Date of Inspection	: 22/09/2022	Est. Duration of Repair	: 5
Inspection At	: COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL) 205 BRADDELL ROAD SINGAPORE 579701		

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,635.77
Revised Amount	:S\$	6,258.10
Check Items (Estimated)	:S\$	6,159.60
Total	:S\$	12,417.70

Lump Sum Repair	:S\$	
-----------------	------	--

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	188,000.00
COE / PARF Rebate	:S\$	103,709.00
Salvage Value	:S\$	
Margin for Repair	:S\$	84,291.00

### **Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost.