

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)
 59 Loyang Drive
 Singapore 508969
 Tel: 6214 8300

Lkk

TP INSURER:
CTPL

EQ Insurance Company Ltd (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	21/09/2022
Vehicle Reg. No.:	SHB4019R	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Vehicle Reg. Date:	28/01/2021
Vehicle Colour:	BLUE		
Engine No:	G4LEKU419199	Chassis No:	KMHC851CVLU192555
Odometer:	172899 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	4,779.44
Miscellaneous Items	0.00
Labour	1,820.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	6,599.44
+ GST 7.00% (S\$)	461.96
Nett Amount (S\$)	7,061.40

This claim is handled by: CHIANG LIAT CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 22 Sep 2022)**Parts:** 143 HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHB4019R/22/09/2022 09:07**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER X Repair	20.00	0.00	*481.10 FL
2	1		*FRONT BUMPER BRACKET LH X	20.00	0.00	*35.00 FL
3	1		*FRONT BUMPER GRILLE LH / SGR	20.00	0.00	*93.45 FL
4	1		*FRONT FENDER LH X Repair	20.00	0.00	*588.80 FL
5	1		*FRONT FENDER EMBLEM LH / R.C.	20.00	0.00	*26.60 FL
6	1		*FRONT FENDER SHIELD LH X	20.00	0.00	*164.70 FL
7	1		*FRONT DAY LIGHT LH X	20.00	0.00	*642.50 FL
8	1		*HEAD LAMP LH / SGR	20.00	0.00	*2,110.30 FL
9	1		*FRONT WING MIRROR ASSY LH / Cut	20.00	0.00	*1,391.70 FL
10	1		*FRONT WHEEL COVER LH / SGR	20.00	0.00	*346.40 FL
11	1		*FRONT DOOR COMFORT LOGO STICKER / R.C.	0	0.00	*75.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **5,955.55**- List Item Discount on L Items (\$\$) **1,176.11**Total Parts (\$\$) **4,779.44**

ComfortDelGro Engineering Pte Ltd/SHB4019R/22/09/2022 09:07. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	700 900.00
2	SPRAY PAINT	New	750 800.00
3	CHECK LIGHTING	New	30 60.00
4	RESET FRONT WHEEL ALIGNMENT	New	60 60.00
Gross Labour Cost (\$)			1,820.00

ComfortDelGro Engineering Pte Ltd/SHB4019R/22/09/2022 09:07. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

4 Days.

P/P

before paint photos.

Gua & up

4pm

22/9/22

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To do a full body inspection during resurvey
- Provide a written report of the information
- Third party's claim on a "Without Prejudice" basis
- No litigation to be brought forward
- Supplemental claim to be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: