



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref: CS3/ASM22009358/Gvy3

8 SHENTON WAY #24-01

Date: 22/09/2022

AXA TOWERSINGAPORE 068811

Code: ASM

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SKR 3108D	Veh. Inspected	GBE 1720Z
Policy No.		Coverage (\$)	0.00
Claim No.	S2M04BFN	Excess (\$)	0.00
Assign From	LOH Cynthia	Assign Date	22/09/2022

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	20/09/2022	Inspection Date	23/09/2022
Survey held at	DERRICK MOTOR WORKS BLK 9002 #01-72 TAMPINES ST 93 SINGAPORE 528836		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--